| Date | Employee | County Roads | | Material | Equip Used |
|----------|------------------------|---|--|------------------------------------|----------------------------|
| 01/02/20 | Kenny/Darrell Nolan | 2301/2312 | Cut tree hauled off, burn dirt to | | 26, 27. 28 |
| 01/02/20 | Bill/Mike | 2437/2312/2301 2316/2319/2318 | Dudly Patched, misc | 9 yds millings | 25, 24, case backhoe |
| 01/03/20 | Bill/Mike | 2507/2715/2807 2708 | Hauled off tree limbs, picked up couch 2807, patched | 2 yds millings | Case backhoe, 25, 24 |
| 01/03/20 | Kevin | 2507 Myrtle Springs, 2602 | Patched | 2yds millings | 22 |
| 01/03/20 | Kenny/Nolan | 2715/2712 | Blade roads, Patched | 14 yds rock, 1 yd millings | 120H, 22A |
| 01/06/20 | Kevin | 2807/2813/2819 | Patched | 3 yds oil sand | 22 |
| 01/06/20 | Mike/Bill | 2703/2721 | Patched | 4 yds oil sand | 22A |
| 01/06/20 | Kenny/Darrell | Hino to tyler and picked up tires | | | 27, 24 |
| 01/07/20 | Kevin/Nolan | 2501/2112/2317 2323 | Patched | 3 yds oil sand | 22 |
| 01/07/20 | Mike/Bill | 2703/2721/2718 2719/2705/2316 | Patched | 1 yd millngs, 4 yds oil sand | 24 |
| 01/07/20 | Kenny/Darrell | 2723/2712/2708 | Blade roads | 42 yds rock | 120M, 27, SDLG |
| 01/08/20 | Kevin/Nolan | 2415/2208 Myrtle Springs | Patched | 4 yds oil sand | 22 |
| 01/08/20 | Kenny/Darrell | Pile Rock | | | |
| 01/08/20 | Bill/Mike | 2624/2630/2631 2316 | Patched | 2 yds millings | 26, 23, 24 |
| 01/09/20 | Mike/Bill | 2115/2924/2914 2915 | Patched | 4 yds oil sand | 24 |
| 01/09/20 | Kevin/Nolan | 2602 | Patched | 4 yds oil sand | 22 |
| 01/09/20 | Kenny/Darrell | Picked up asphalt, went to tyler, tires | | | |
| 01/10/20 | Mike/Bill | 2301/2303/2219 | Patched/barn | 2yd oil sand | 24 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------------|--|---|--------------------|--|
| 01/10/20 | Kevin/Nolan | - 2 2508 | Patched, change oil in 22A, worked in shop | 1 yd oil sand | 22A |
| 01/10/20 | Kenny/Darrell | Worked in yard | m snop | | |
| 01/13/20 | Bill/Nolan | 2112/2816/2604 2622/2704 | Patched, cut up tree 2112 | 2 yds oil sand | 22A, 21 |
| 01/13/20 | Kenny/Mike Darrell | Worked in shop picked up mix, worked on backhoe, 27 | | | |
| 01/14/20 | Nolan | 2918/2120 | Put up bridge signs 2918 patched | 1 ½ yd oil sand | 22A |
| 01/14/20 | Kenny/Mike Bill | 2534 | Cleaned out ditches | | Gradall, 26, 27 |
| 01/14/20 | Kevin | 2922 | Boomaxe | | Booaxe |
| 01/15/20 | Bill/Mike/ Kenny | 2534 | Clean out ditch | | Gradall, 26, 28 |
| 01/15/20 | Kevin | 2922/2918 | Boomaxe | | Boomaxe |
| 01/15/20 | Nolan | 2918 | Patched | 2 yds oil sand | 22A |
| 01/16/20 | Nolan | 2409/2314/2705 | Cut tree, patch, worked on backhoe | 2 yds oil sand | 21A |
| 01/16/20 | Kevin/Bill | 2908's/2300's | Patched | 1 yd millings | 22 |
| 01/16/20 | Kenny/Darrell | | Took 26 to Tyler for repair | | 26/20B |
| 01/17/20 | Bill/Kevin Nolan | 2112/2700's/ 2500's 2300's | Cut up trees 2112, patched | 3 yds oil sand | Haul truck, case backhoe22 2A, 22 |
| 01/17/20 | Kenny/Mike | Worked on boomaxe | | | |
| 01/21/20 | Bill/Kevin | 2700's/2900's | Patched | 2 yds millings | 24 |
| 01/21/20 | Mike/Kenny | Worked on 28, backhoe, fixed tires | | | |
| 01/21/20 | Kevin/Nolan | 2100's/2500's | Patched | 2 yds oil sand | 22A |
| 01/22/20 | Kevin/Nolan | Myrtle S/2520 | Patched | 1 ½ yd mills | 22A |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|---------------------------|--|--|--------------------|---|
| 01/22/20 | Bill/Kevin R | 2300's/2800's | Patched | 2 yds millings | 24, 22 |
| 01/22/20 | Kenny/Mike Darrell | Took gradall to BJ for tires, 23 to tyler for repair, cleaned shop | | | 20B, gradall, 23 |
| 01/23/20 | Nolan | 2205/2520 | Patched/ put up road signs | 2 yds millings | 22A |
| 01/23/20 | Bill/Kevin | 2802/2808/2809 2403/2404/2434 2807 | Patched | 3 yds oil sand | 22 |
| 01/23/20 | Kenny/Darrell Mike | Worked in shop, changed tires, gradall, 24 | | | 20B, 24, case loader |
| 01/24/20 | Kenny/Mike | 2719 | Patched, to plant for mix | 1 ½ | 27, 22 |
| 01/24/20 | Bill/Kevin | 2412/2434/2409 2414 | Patched | 2 yds oil sand | 24, patch truck 24 |
| 01/24/20 | Nolan/Kevin | 2205/2511/2219 2534 | Patched | 2 yds oil sand | 22 |
| 01/27/20 | Bill/Mike/ Nolan/Kevin | Installed 15x24 2120/12x24 2624, | Patched installed culverts | 49 yds rock | 26, 27, 28 24, 22 case backhoe |
| 01/27/20 | Kevin | 2120/2147/2101 | Patched | 2 ½ yd oil sand | 22A |
| 01/28/20 | Kevin/Bill | 2400's/2500's | Patched | 2 yds oil sand | 24 |
| 01/28/20 | Kevin t/Nolan | 2410/Myrtle Springs | Patched | 2 yds oil sand | 22A |
| 01/28/20 | Kenny/Mike | 2120/2100's | Patched, worked on 22, patched trash | 1 yd oil sand | 22, backhoe |
| 01/29/20 | Nolan/Kevin | 2219/2301/2421 | Patch | 2 yds oil sand | 22A |
| 01/29/20 | Bill/Kevin | 2721/2702/2918 2916/2316/2703 | Patch | 3 yds oil sand | 24 |
| 01/29/20 | Kenny/Mike | Worked in shop, repaired 20B, picked up Gradall | | | 20B, 22, big loader |
| 01/30/20 | Mike/Nolan | 3447/2120/2101 Cherry ck | Patch | 3 yds oil sand | 22A |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| O1/30/20 Bill/Kevin 2302/2129/2146 Patched 2901/2909 Patched 2901/2909 Patched sand 24, 23 sand 201/30/20 Kenny/Darrell Picked up 23 in tyler and hydrallic part Patched 2 yds oil sand 24, 23 Patched Patched 2 yds oil sand 24, 23 Patched Patched 2 yds oil sand 24, 23 Patched 2 yds oil sand 24, 24, 24, 24, 24, 24, 24, 24, 24, 24, | Date | Employee | County Roads | Work Done | Material | Equip Used |
|--|------------|-------------------|---------------------|----------------|---------------|-------------------|
| O1/30/20 Kenny/Darrell 6620/6605 Put up PR 2 post/2 20B | | T | - 4 | - | T | |
| Signs, checked Signs | 01/30/20 | Bill/Kevin | | Patched | - | 24, 23 |
| O1/31/20 | 01/30/20 | Kenny/Darrell | 6620/6605 | Put up PR | 2 post/2 | 20B |
| 01/31/20 Kenny/Darrell vyler and hydralile part 20B 01/31/20 Mike/Nolan 3447/2417 Patched 2 yds oil sand 22A 01/31/20 Bill/Kevin 2909/2311/2923 oil sand 2 yds oil sand 26, 22 sand 02/03/20 Woody 2427/2437/2410 oxlusty 2415/2416 oxlusty 2418/2416/2416 oxlusty 2414/2415/2416 oxlusty 2418/2420/2422 Patch 2 yds oil sand sand 22A 02/03/20 Kenny/Mike Colling oxlusty 2708/2723/2717 Plade roads 77 yds rock sand 120H, 27 02/03/20 Kenny/Mike Kevin Nolan 2122/2120 sand 12x40, 2120 Installed 15x24, 2122 sand 12x40, 2120 35 yds rock 26, 27, 23, backhoe 26, 27, 23, backhoe 02/04/20 Nolan/Wood 2708/2721/2705 Patch 2 yds oil sand 24, backhoe 02/04/20 Bill/Kiven Myrtle Springs, 2501/2119/2404 picked up mix 2 yds rock 22A 22A 02/04/20 Kenny/ Mike 2602 Worked on boomaxe, patched 1 yd oil sand 24, sand 24, sand 24, sand 24, sand 25, sand 24, sand 25, sand 26, 22 sand 24, sand 25, sand 26, sand 26, sand 26, sand 27, | | | | signs, checked | signs | |
| tyler and hydralile part hydralile part Patched 2 yds oil sand 22A | 01/31/20 | Kenny/Darrell | Picked up 23 in | Toaus | | 20B |
| Date | 01/31/20 | Kenny/Darren | - | | | 200 |
| 01/31/20 Mike/Nolan 3447/2417 Patched 2 yds oil sand 22A 01/31/20 Bill/Kevin 2909/2311/2923 (2415 Oil sand 2 yds oil sand 26, 22 sand 02/03/20 Woody 2427/2437/2410 (2418/2420/2422) Patch 2 yds oil sand 22A 02/03/20 Kenny/Mike 2708/2723/2717 Blade roads 77 yds rock 120H, 27 02/03/20 Bill/Kevin Myrtle Springs Patched 3 ½ yds oil sand 22 02/03/20 Kenny/Mike Kevin/Nolan Myrtle Springs Patched 3 ½ yds rock 26, 27, 23, backhoe 02/04/20 Kenny/Mike Kevin/Nolan Myrtle Springs, 2501/2119/2404 picked up mix Patch 3 yds oil sand 26, 22 sand 02/04/20 Kenny/Mike Myrtle Springs, 2501/2119/2404 picked up mix Patched 3 yds oil sand 26, 22 sand 02/04/20 Kenny/Mike Myytle Springs, 2400's/2500's Patched 3 yds oil sand 24 02/06/20 Bill/Kevin Worked in shop on 20B, 20 Patched 3 yds oil sand 24 02/07/20 Bill | | | • | | | |
| Sand | 01/31/20 | Mike/Nolan | | Patched | 2 vds oil | 22A |
| 2415 | 01/21/20 | TVIIIIO/ I VOIGII | 31172117 | T division | - | |
| 2415 | 01/31/20 | Bill/Kevin | 2909/2311/2923 | Oil sand | 2 yds oil | 26, 22 |
| 2414/2415/2416 2418/2420/2422 2418/2420/2422 2708/2723/2717 Blade roads 77 yds rock 120H, 27 02/03/20 Bill/Kevin Myrtle Springs Patched 3½ yds oil sand 35 yds rock 26, 27, 23, backhoe 15x24, 2122 and 12x40, 2120 2100 2708/2721/2705 Patch 2 yds rock 26, 27, 23, backhoe 2708/2721/2705 Patch 2 yds rock 26, 22 22 22 23 23 23 24 24 | | | 2415 | | | , |
| 2418/2420/2422 | 02/03/20 | Woody | 2427/2437/2410 | Patch | 2 yds oil | 22A |
| 02/03/20 Kenny/Mike 2708/2723/2717 Blade roads 77 yds rock 120H, 27 02/03/20 Bill/Kevin Myrtle Springs Patched 3 ½ yds oil sand 22 02/04/20 Kenny/Mike Kevin/Nolan 2122/2120 Installed 15x24, 2122 and 12x40, 2120 35 yds rock 26, 27, 23, backhoe 02/04/20 Nolan/Wood 2708/2721/2705 Patch 2 yds rock 22A 02/04/20 Bill/Kiven Myrtle Springs, 2501/2119/2404 picked up mix Patch 3 yds oil sand 26, 22 sand 02/04/20 Kenny/ Mike 2602 Worked on boomaxe, patched 1 yd oil sand 24 02/06/20 Bill/Kevin Myytle Springs, 2400°s/2500°s Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Finished install culverts, patched 14 yds rock, cut up tree culverts, patched Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 2514/2148/2620 Patched 3 yds millings 22A 02/10/20 Bill/Kevin 2300°s/2400°s Patched 3 yds millings 22A </td <td></td> <td>·</td> <td>2414/2415/2416</td> <td></td> <td>sand</td> <td></td> | | · | 2414/2415/2416 | | sand | |
| 02/03/20 Bill/Kevin Myrtle Springs Patched 3 ½ yds oil sand 22 02/04/20 Kenny/Mike Kevin/Nolan 2122/2120 Installed 15x24, 2122 and 12x40, 2120 35 yds rock 26, 27, 23, backhoe 02/04/20 Nolan/Wood 2708/2721/2705 Patch 2 yds rock 22A 02/04/20 Bill/Kiven Myrtle Springs, 2501/2119/2404 picked up mix Patch 3 yds oil sand 26, 22 sand 02/04/20 Kenny/ Mike 2602 Worked on boomaxe, patched 1 yd oil sand 24 02/06/20 Bill/Kevin Myytle Springs, 2400°s/2500°s Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Finished install culverts, patched 14 yds rock, cut up tree 2217, 1 yd patched Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 22A 02/10/20 Bill/Kevin 2300°s/2400°s Patched 3 yds millings 22A 02/10/20 Kenny/Mike Worked in shop 3 yds millings 22A | | | 2418/2420/2422 | | | |
| Sand | 02/03/20 | Kenny/Mike | 2708/2723/2717 | Blade roads | 77 yds rock | 120H, 27 |
| 02/04/20 Kenny/Mike Kevin/Nolan 2122/2120 Installed 15x24, 2122 and 12x40, 2120 35 yds rock backhoe 26, 27, 23, backhoe 02/04/20 Nolan/Wood 2708/2721/2705 Patch 2 yds rock 22A 02/04/20 Bill/Kiven Myrtle Springs, 2501/2119/2404 picked up mix Patch 3 yds oil sand 26, 22 sand 02/04/20 Kenny/Mike Kenny/ Mike 2602 Worked on boomaxe, patched 3 yds millings 24 02/06/20 Kenny/Mike Myytle Springs, 2400° s/2500° s Patched 3 yds millings 24 02/07/20 Kenny/Mike Worked in shop on 20B, 20 Finished install culverts, patched 14 yds rock, cut up tree culverts, patched Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 2514/2148/2620 Patched 3 yds millings 22A 02/10/20 Bill/Kevin 2300° s/2400° s Patched 3 yds millings 24 02/10/20 Kenny/Mike Worked in shop Patched 3 yds millings 22A | 02/03/20 | Bill/Kevin | Myrtle Springs | Patched | _ | 22 |
| Kevin/Nolan | | | | | | |
| and 12x40, 2120 | 02/04/20 | | 2122/2120 | | 35 yds rock | |
| 02/04/20 Nolan/Wood 2708/2721/2705 Patch 2 yds rock 22A 02/04/20 Bill/Kiven Myrtle Springs, 2501/2119/2404 picked up mix Patch 3 yds oil sand 26, 22 sand 02/04/20 Kenny/ Mike 2602 Worked on boomaxe, patched 1 yd oil sand 24 02/06/20 Bill/Kevin Myytle Springs, 2400's/2500's Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 It yds rock, cut up tree culverts, patched Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 02/10/20 Kenny/Mike Worked in shop 224 | | Kevin/Nolan | | · · | | backhoe |
| 02/04/20 Nolan/Wood 2708/2721/2705 Patch 2 yds rock 22A 02/04/20 Bill/Kiven Myrtle Springs, 2501/2119/2404 picked up mix Patch 3 yds oil sand 26, 22 02/04/20 Kenny/ Mike 2602 Worked on boomaxe, patched 1 yd oil sand 24 02/06/20 Bill/Kevin Myytle Springs, 2400's/2500's Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Finished install culverts, patched 14 yds rock, cut up tree culverts, patched Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 2514/2148/2620 Patched 3 yds millings 22A 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 millings 02/10/20 Kenny/Mike Worked in shop 22, 22, | | | | · | | |
| 02/04/20 Bill/Kiven Myrtle Springs, 2501/2119/2404 picked up mix Patch 3 yds oil sand 26, 22 02/04/20 Kenny/ Mike 2602 Worked on boomaxe, patched 1 yd oil sand 24 02/06/20 Bill/Kevin Myytle Springs, 2400's/2500's Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Finished install culverts, 2217, 1 yd patched Haultruck, backhoe, patched haultruck, backhoe, patched 02/07/20 Woody 2147/2128/2602 2514/2148/2620 Patched 3 yds millings 22A 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 02/10/20 Kenny/Mike Worked in shop 222, | 02/04/20 | Nalar /Waad | 2709/2721/2705 | | 2 rado no als | 22.4 |
| 2501/2119/2404 sand sand | 02/04/20 | Notan/wood | 2/08/2/21/2/05 | Paten | 2 yas rock | ZZA |
| 2501/2119/2404 sand sand | 02/04/20 | Bill/Kiven | Myrtle Springs, | Patch | 3 yds oil | 26, 22 |
| 02/04/20 Kenny/ Mike 2602 Worked on boomaxe, patched 1 yd oil sand 24 02/06/20 Bill/Kevin Myytle Springs, 2400' s/2500's Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Image: Springs of the patched of the | | | | | • | , |
| Domaxe, patched Domaxe, pa | | | picked up mix | | | |
| 02/06/20 Bill/Kevin Myytle Springs, 2400's/2500's Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Worked in shop on 20B, 20 Worked in shop on 20B, 20 I4 yds rock, cut up tree haultruck, backhoe, millings Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 26, 27 24 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 22A millings 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 millings 02/10/20 Kenny/Mike Worked in shop 22, | 02/04/20 | Kenny/ Mike | 2602 | Worked on | 1 yd oil | 24 |
| 02/06/20 Bill/Kevin Myytle Springs, 2400's/2500's Patched 3 yds millings 24 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Worked in shop on 20B, 20 I4 yds rock, cut up tree install cut up tree patched Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 26, 27 24 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 22A millings 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 02/10/20 Kenny/Mike Worked in shop 22, | | | | boomaxe, | sand | |
| 2400's/2500's millings 02/06/20 Kenny/Mike Worked in shop on 20B, 20 14 yds rock, cut up tree haultruck, backhoe, patched Gradall, haultruck, backhoe, millings 02/07/20 Bill/Mike Kenny/Nolan Darrell 2506/2124/2148 install culverts, patched 2217, 1 yd millings backhoe, millings 02/07/20 Woody 2147/2128/2602 Patched 3 yds millings 22A millings 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 millings 02/10/20 Kenny/Mike Worked in shop 22, | | | | | | |
| 02/06/20 Kenny/Mike Worked in shop on 20B, 20 Image: Control of the | 02/06/20 | Bill/Kevin | | Patched | • | 24 |
| 02/07/20 Bill/Mike Kenny/Nolan Darrell 2120/2217/2507 Finished install cut up tree patched 14 yds rock, cut up tree patched Gradall, haultruck, backhoe, millings 02/07/20 Woody 2147/2128/2602 patched Patched 3 yds millings 22A 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 millings 02/10/20 Kenny/Mike Worked in shop 22, | 0.0 (0.0) | | | | millings | |
| 02/07/20 Bill/Mike Kenny/Nolan Darrell 2120/2217/2507 2506/2124/2148 Finished install culverts, patched 14 yds rock, cut up tree 2217, 1 yd millings Gradall, haultruck, backhoe, millings 02/07/20 Woody 20/207/20 2147/2128/2602 2514/2148/2620 Patched millings 3 yds millings 22A 02/10/20 Bill/Kevin Bill/Kevin 2300's/2400's 2300's/2400's Patched Patched 3 yds millings 24 02/10/20 Kenny/Mike Worked in shop 22, | 02/06/20 | Kenny/Mike | _ | | | |
| Kenny/Nolan Darrell 2506/2124/2148 install cut up tree culverts, patched 2217, 1 yd millings 26, 27 24 | 02/07/20 | D'11 /3 4'1 | | TO: 1 1 | 14 1 1 | G 1 11 |
| Darrell culverts, patched 2217, 1 yd millings 26, 27 24 | 02/07/20 | | | | , | |
| 02/07/20 Woody 2147/2128/2602 2514/2148/2620 Patched millings 3 yds millings 22A 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 millings 02/10/20 Kenny/Mike Worked in shop 22, | | | Z3U6/2124/2148 | | | ′ |
| 02/07/20 Woody 2147/2128/2602 Patched 2514/2148/2620 3 yds millings 22A 02/10/20 Bill/Kevin 2300's/2400's Patched millings 3 yds millings 24 millings 02/10/20 Kenny/Mike Worked in shop 22, | | Danen | | | | |
| 2514/2148/2620 millings | 02/07/20 | Woody | 21/17/2128/2602 | | | |
| 02/10/20 Bill/Kevin 2300's/2400's Patched 3 yds millings 24 02/10/20 Kenny/Mike Worked in shop 22, | 02/07/20 | **Oody | | 1 awied | • | |
| 02/10/20 Kenny/Mike Worked in shop millings 22, | 02/10/20 | Bill/Kevin | | Patched | | 24 |
| 02/10/20 Kenny/Mike Worked in shop 22, | 02/10/20 | 2111/1X0 VIII | 2500 5/2 100 5 | 1 monou | • | |
| | 02/10/20 | Kenny/Mike | Worked in shop | | | 22, |
| Cacino | | Darrell | F | | | backhoe |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| 1972 1972 1972 1972 1972 1973 1974 1974 1975 1974 1975 | Date | Employee | County Roads | | Material | Equip Used |
|--|----------|-----------------|----------------|-----------------|--------------|-------------------|
| O2/12/20 Bill/Kevin 2700's Patched, put up sign 2301 millings 3 yds oil 24 24 24 25 28 26 2808 2816/2808 281 | | 1 | | - | I | |
| 02/12/20 Bill/Kevin 2800's/2700's 2816/2808 Flooded area, patched 2816/2808 Put up high water signs, cut tree 2140 Patched, put up sign 2301 22 22 23 24 24 24 25 25 25 25 25 | | | - | | | |
| O2/12/20 Bill/Kevin 2800's/2700's 2816/2808 Put up high water signs, cut tree 2140 Put up high water signs, cut ree 2140 Put up sign millings, 1 yd oil sand 222 Put up sign millings, 1 yd oil sand Put up high water signs, cut ree 2140 Put up sign millings, 1 yd oil sand Put up sign millings, 1 yd oil sand Put up sign millings, 1 yd oil sand Put up high water signs, cut ree 2140 Put up sign millings, 1 yd oil sand Put up sign millings, 1 | 02/11/20 | Bill/Kevin | 2700's | _ | • | 24 |
| 2816/2808 flooded area, patched 22 | | | | | | |
| Description | 02/12/20 | Bill/Kevin | | | • | 24 |
| 02/12/20 Nolan/Mike 2112/2139/2146 Put up high water signs, cut tree 2140 22 02/13/20 Woody/Mike 2908/2911/2208 Patched, put up sign 2139/2112 1 yd millings, 1 yd oil sand 22 02/13/20 Kenny/Darrell 2506 Patched 1 yd millings, 1 yd oil sand 22A, 20B millings, 1 yd oil sand 02/13/20 Bill/Kevin 2800's, 2205/2202/2201 Patched 1 yd millings, 1 yd oil sand 24 millings, 1 yd oil sand 02/14/20 Woody/Nolan 2146/2112/2116 2501/2311 Patched 2 yds oil sand 22A 02/14/20 Bill/Kevin 2301/2310/2311 2300/2311 2300/2313 Patched 2 yds oil sand 24 sand 02/14/20 Kenny/Mike Darrell 2507/2908/2303 250/2908/2303 Repaired washout 2507 sand 27, 120H 02/18/20 Kenny/Bill Nolan 2317/2502/2201 218 2705/2816 2705 Patched 14 yds rock, failures, 2317, patched 26, 24 sand 02/18/20 Woody 2718/2705/2816 2705 Patched 21 yds rock Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A | | | 2816/2808 | flooded area, | sand | |
| 02/13/20 | | | | patched | | |
| O2/13/20 | 02/12/20 | Nolan/Mike | 2112/2139/2146 | Put up high | | 22 |
| 02/13/20 Woody/Mike 2908/2911/2208 2209/2504/2511 up sign 2139/2112 yd oil sand 1 yd millings, 1 yd oil sand 22 02/13/20 Kenny/Darrell 2506 Patched 1 yd millings, 1 yd oil sand 22A, 20B millings, 1 yd oil sand 02/13/20 Bill/Kevin 2800's, 205/2202/2201 Patched 1 yd millings, 1 yd oil sand 24 millings, 1 yd oil sand 02/14/20 Woody/Nolan 2146/2112/2116 2501/2319 Patched 2 yds oil sand 22A sand 02/14/20 Bill/Kevin 2301/2310/2311 /2309/2313 Patched 2 yds oil sand 24 sand 02/14/20 Kenny/Mike Darrell 2507/2908/2303 Repaired washout 2507 sand 28 yds oil sand 27, 120H 02/18/20 Kenny/Bill Nolan 2317/2502/2201 Repaired base failures, 2317, patched 14 yds rock, 1 yd oil sand 26, 24 sand 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 22A sand 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock sand Case backhoe, 23, 27 02/19/20 Mike/Bill Kevin 2120/2115/2519 Patched | | | | water signs, | | |
| 2209/2504/2511 | | | | cut tree 2140 | | |
| 02/13/20 Kenny/Darrell 2506 Patched 1 yd 22A, 20B millings 2205/2202/2201 Patched 1 yd 24 millings 1 yd oil sand 24 millings 1 yd oil sand 24 2501/2502/2411 2501/2502/2411 2501/2502/2411 2501/2139 Patched 2 yds oil sand 22A 24 2501/2502/2411 2501/2139 Patched 2 yds oil sand 24 2501/24/20 Renny/Mike 2507/2908/2303 Repaired 28 yds oil sand 27, 120H 202/14/20 Kenny/Mike Darrell 2317/2502/2201 Repaired base failures, 2317, patched 24 yds oil sand 27, 120H 26, 24 2705 Patched 2 yds oil sand 26, 24 2705 Patched 2 yds oil sand 27, 120H 26, 24 2705 Patched 2 yds oil sand 22A 2705 Patched 2 yds oil sand 202/19/20 Patched 2 yds oil sand 202/19/20 Patched 2 yds oil sand 202/19/20 Patched 2 yds oil sand 2 yds oil sand | 02/13/20 | Woody/Mike | 2908/2911/2208 | Patched, put | 1 yd | 22 |
| 02/13/20 Kenny/Darrell 2506 Patched 1 yd millings 22A, 20B millings 02/13/20 Bill/Kevin 2800's, 2205/2202/2201 Patched 1 yd millings, 1 yd oil sand 24 02/14/20 Woody/Nolan 2146/2112/2116 2501/2502/2411 2501/2319 Patched 2 yds oil sand 22A 02/14/20 Bill/Kevin 2301/2310/2311 /2309/2313 Patched 2 yds oil sand 24 02/14/20 Kenny/Mike Darrell 2507/2908/2303 Repaired washout 2507 28 yds oil sand 27, 120H 02/18/20 Kenny/Bill Nolan 2317/2502/2201 Repaired base failures, 2317, patched 14 yds rock, 1 yd oil sand 26, 24 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 22A 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches 2 yds oil sand 22A 02/19/20 < | | | 2209/2504/2511 | up sign | millings, 1 | |
| December 202/13/20 Bill/Kevin 2800°s, 2205/2202/2201 Sill/Kevin 24 Millings, 1 yd oil sand 2501/2502/2411 2501/2139 Sand 22A Sand 22A Sand 24 Sand 2501/2139 Sand 24 Sand 2501/2139 Sand 24 Sand | | | | 2139/2112 | yd oil sand | |
| 02/13/20 Bill/Kevin 2800's, 2205/2202/2201 Patched 1 yd millings, 1 yd oil sand 02/14/20 Woody/Nolan 2146/2112/2116 2501/2502/2411 2501/2139 Patched 2 yds oil sand 22A 02/14/20 Bill/Kevin 2301/2310/2311 /2309/2313 Patched 2 yds oil sand 24 yds oil sand 02/14/20 Kenny/Mike Darrell 2507/2908/2303 washout 2507 Repaired washout 2507 28 yds oil sand 02/18/20 Kenny/Bill Nolan Nolan 2317/2502/2201 Patched Repaired base failures, 2317, patched 1 yd oil sand 02/18/20 Woody 2718/2705/2816 Patched 2 yds oil sand 27, 120H 02/18/20 Woody 2718/2705/2816 Patched 2 yds oil sand 26, 24 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 2 yds oil sand 22 A 02/19/20 Nolan 2906/2307/2311 Patched 21 yds rock backhoe, 23, 27 Case backhoe, 23, 27 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches 1 yd oil sand Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenn | 02/13/20 | Kenny/Darrell | 2506 | Patched | 1 yd | 22A, 20B |
| 2205/2202/2201 millings, 1 yd oil sand | | | | | millings | |
| O2/14/20 Woody/Nolan 2146/2112/2116 Patched 2 yds oil sand 22A 2501/2502/2411 2501/2139 Patched 2 yds oil sand 24 2501/2139 Patched 2 yds oil sand 24 2309/2313 Patched 28 yds oil sand 27, 120H O2/14/20 Kenny/Mike Darrell 2317/2502/2201 Repaired base 14 yds rock Gradall, 27, 120H Nolan Patched 2 yds oil sand 27, 120H 26, 24 26, 24 26, 24 26, 24 2705 210/218/20 Mike/Nolan 2627 Installed 15x24 culvert 15x24 culvert Sand 21 yds rock Case backhoe, 23, 27 02/19/20 Mike/Bill 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 24 24 24 24 24 24 2 | 02/13/20 | Bill/Kevin | 2800's, | Patched | 1 yd | 24 |
| 02/14/20 Woody/Nolan 2146/2112/2116 2501/2502/2411 2501/239 Patched 2 yds oil sand 22A 02/14/20 Bill/Kevin 2301/2310/2311 /2309/2313 Patched 2 yds oil sand 24 02/14/20 Kenny/Mike Darrell 2507/2908/2303 Repaired washout 2507 28 yds oil sand Gradall, 27, 120H 02/18/20 Kenny/Bill Nolan 2317/2502/2201 Repaired base failures, 2317, patched 14 yds rock, Gradall, 1 yd oil sand 26, 24 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 26, 24 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/ | | | 2205/2202/2201 | | millings, 1 | |
| 2501/2502/2411 2501/2139 24 2501/2139 24 24 202/14/20 Bill/Kevin 2301/2310/2311 Patched 2 yds oil sand 27, 120H 26, 24 27, 120H 26, 24 2705 270 | | | | | yd oil sand | |
| 2501/2139 24 24 2301/2310/2311 24 2309/2313 24 2309/2313 24 2309/2313 24 24 2309/2313 24 24 2309/2313 24 24 24 24 24 24 24 2 | 02/14/20 | Woody/Nolan | 2146/2112/2116 | Patched | 2 yds oil | 22A |
| 02/14/20 Bill/Kevin 2301/2310/2311 Patched 2 yds oil sand 24 02/14/20 Kenny/Mike Darrell 2507/2908/2303 Repaired washout 2507 28 yds oil sand Gradall, 27, 120H 02/18/20 Kenny/Bill Nolan 2317/2502/2201 Repaired base failures, 2317, patched 14 yds rock, 1 yd oil sand Gradall, 26, 24 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 22A 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | | 2501/2502/2411 | | sand | |
| 102/14/20 Kenny/Mike 2507/2908/2303 Repaired 28 yds oil 3 yas oil 27, 120H | | | 2501/2139 | | | |
| 02/14/20 Kenny/Mike Darrell 2507/2908/2303 Repaired washout 2507 28 yds oil sand Gradall, 27, 120H 02/18/20 Kenny/Bill Nolan 2317/2502/2201 Repaired base failures, 2317, patched 14 yds rock, 1 yd oil sand Gradall, 26, 24 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 22A 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/14/20 | Bill/Kevin | 2301/2310/2311 | Patched | 2 yds oil | 24 |
| Darrell | | | /2309/2313 | | sand | |
| 02/18/20 Kenny/Bill Nolan 2317/2502/2201 Repaired base failures, 2317, patched 14 yds rock, 1 yd oil sand Gradall, 26, 24 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 22A 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock backhoe, 23, 27 Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 sand 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/14/20 | Kenny/Mike | 2507/2908/2303 | Repaired | 28 yds oil | Gradall, |
| Nolan | | Darrell | | | sand | 27, 120H |
| 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 22A 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock 23, 27 Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/18/20 | Kenny/Bill | 2317/2502/2201 | Repaired base | 14 yds rock, | Gradall, |
| 02/18/20 Woody 2718/2705/2816 2705 Patched 2 yds oil sand 22A 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock backhoe, 23, 27 Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 sand 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | Nolan | | failures, 2317, | 1 yd oil | 26, 24 |
| 2705 Sand Sand | | | | patched | sand | |
| 02/18/20 Mike/Nolan Kevin 2627 Installed 15x24 culvert 21 yds rock backhoe, 23, 27 Case backhoe, 23, 27 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 sand 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/18/20 | Woody | 2718/2705/2816 | Patched | 2 yds oil | 22A |
| Kevin 15x24 culvert backhoe, 23, 27 | | | 2705 | | sand | |
| 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/18/20 | Mike/Nolan | 2627 | Installed | 21 yds rock | Case |
| 02/19/20 Nolan 2906/2307/2311 Patched 2 yds oil sand 22A 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | Kevin | | 15x24 culvert | | backhoe, |
| 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | | | | | 23, 27 |
| 02/19/20 Mike/Bill Kevin 2139 Cleaned out ditches Case backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/19/20 | Nolan | 2906/2307/2311 | Patched | 2 yds oil | 22A |
| Kevin ditches backhoe, 26, 23 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | | | | sand | |
| 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/19/20 | Mike/Bill | 2139 | Cleaned out | | Case |
| 02/19/20 Bill/Kevin 2120/2115/2519 Patched 1 yd oil sand 24 02/19/20 Kenny/Darrell Mike Checked roads, worked on 20 One door latch, headlight 20, gradall 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | Kevin | | ditches | | backhoe, |
| Sand Sand O2/19/20 Kenny/Darrell Checked roads, One door latch, headlight O2/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | | | | | 26, 23 |
| 02/19/20Kenny/Darrell MikeChecked roads, worked on 20One door latch, headlight20, gradall02/20/20Woody/Nolan2517/2511/2516Patched3 yds oil22A | 02/19/20 | Bill/Kevin | 2120/2115/2519 | Patched | 1 yd oil | 24 |
| Mike worked on 20 latch, headlight 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | | | | sand | |
| Mike worked on 20 latch, headlight 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | 02/19/20 | Kenny/Darrell | Checked roads, | | One door | 20, gradall |
| 02/20/20 Woody/Nolan 2517/2511/2516 Patched 3 yds oil 22A | | | worked on 20 | | latch, | |
| | | | | | headlight | |
| | 02/20/20 | Woody/Nolan | 2517/2511/2516 | Patched | 3 yds oil | 22A |
| 2434 sand | | | 2434 | | sand | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|--------------------------|---|--|--|---|
| 02/20/20 | Bill/Kevin | 2120/2102/2520 | 2414, Patched | 4 yds oilsand | 24 |
| 02/20/20 | Kenny/Mike | 2317/2139 | Speed limit signs 2317, clean ditches 2139, worked on 120H | 1 radio, 2 signs, 2 post, | 20B, 28, backhoe, 120H gradall |
| 02/21/20 | Mike/Kenny Nolan | Cherry blossom, 2101, 2204 | Patched, overlay 2204 with millings | 1 yd oil sand, 84 yds of millings | 120H, 26, 27, 22A |
| 02/21/20 | Bill/Kevin | 2411/2414/2300 's | Cleaned on ditches | 1 yd oil sand | Bachoe, 23, 26 |
| 02/24/20 | Bill/Kevin | 2718/2719/2908 | Patched, pick up mix Malikoff repaired culvert | | 26, 23, 28, 24, backhoe |
| 02/24/20 | Kenny/Mike Darrell | 2128/2129 | Blade road | 77 yds rock | 120H, 23, 27 |
| 02/24/20 | Woody/Nolan | 2504/2816/2506 2507 | Patched | 2 yds oil sand | 22A |
| 02/25/20 | Kenny/Nolan Mike | 2923/2802/2801 | Strip patched, 2923, level up bridge 2802, patched 2801 | 5 flowboys, 125 tons of wood county oil sand | 120M, 26, 27 |
| 02/25/20 | Bill/Kevin | 2721/2706/2705 2708/2704 | Patched | 4 yds oil sand, 1 yd millings | 24 |
| 02/25/20 | Woody | 2704/2507/2120 2145/2602/2701 2710/2709 | Patched | 2 yds oil sand | 22A |
| 02/26/20 | Woody | 2802/2804/2806 2810/2807/2815 | Patched | 3 yds oil sand | 24 |
| 02/26/20 | Kenny/Mike Bill | 2128 | Blade road | 77 yds rock | 120H, 26, 27 |
| 02/27/20 | Woody/Kevin | 2307/2306/2304 2720 | Patched | 3 yds oil sand | 24 |
| 02/27/20 | Kenny/Bill Nolan/Mike | 2623 | Blade road | 91 tons rock | 120H, 26, 27, 28 |
| 02/28/20 | Kevin/woody | 2627/2629/2503 2506/2507 | Patched | 3 yds oil sand | 24 |
| 02/28/20 | Kenny/Mike Bill/Nolan | 2503/2504 | Installed 12x30, 2503, | 36 yds rock, 1 yd oil | Backhoe, 26, 27, 28 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

Date Employee County Roads Work Done Material Equip Used 15x24, 2504 sand Nolan/Woody 03/02/20 2505/2414/2501 Patch 2 yds oil 21A sand 2708/2709 35 yds rock 03/02/20 Darrell/Kenny Installed 27, 28, Mike/Bill 15x20, 2709, backhoe. repaired base haultruck failure 2708. cleaned brush 2708 03/03/20 Kenny/Darrell 2212/2201 Added 3 ft to 21 yds Backhoe, millings Mike culvert, put 30 haultruck, mph sign on 28, 21A 2201 03/03/20 Bill/Nolan 2416/2304/2303 Patched 3 yds oil 22A 2305/2306/2312 sand 2311 Bill/Kevin 03/04/20 2317/help cut Picked up 21A voting boxes up tree Mike/Nolan 2410/2602/2317 Patched, cut 1 yd oil 22 03/04/20 tree off 2317 sand 03/05/20 Nolan/Woody 2702/2602/2807 3 yds oil 22A Patch sand 03/05/20 Bill/Kevin 3 yds oil 24 2318/2319/2912 Patch 2301 sand Kenny/Mike 03/05/20 2312/2623/2622 Clean log jam 7 yds Backhoe, 2903 2312, patched millings, 28, 120H 03/06/20 Bill/Kevin 2316/2813/2802 Patched, filled 21 yds Backhoe, holes tank car millings, 1 23 24 2316 yd oil sand 2501/2414/ Nolan/Woody Patched 22A 03/06/20 3 yds oil Cherry Ck sand 03/06/20 Kenny/Mike Piled Rock SDLG 1 yd oil Keivn/Woody 24 03/09/20 2302 Patched Dayten sand 03/09/20 Kenny/Darrell 2705/2708/2717 Blade roads 28 yds rock 120M, 28, backhoe 2710 2301/2802/2807 2 yds oil 03/09/20 Nolan/Woody Patched 22A Cherry Blossom sand Mike/Bill 03/09/20 2317 Picked up Haul Dayten/Kevin brush piles, truck, dug out ditch, backhoe, 25, 26, 24 cut up trees 03/10/20 Nolan/Woody 2703/2703/2721 Patch 2 yds oil 22A 2702 sand

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| - 8 - 03/10/20 Bill/Mike 2716/2801/2115 Repaired base 14 yd rock, Gradal failures 1 yd oil 28, 22 | 1, |
|--|------|
| failures 1 yd oil 28, 22 | 1, |
| | |
| | |
| sand | |
| 03/10/20 Kevin/Dayten 2413/2812/2901 Patched 3 yds oil 24 | |
| 2903/2909 sand | 27 |
| 03/10/20 Kenny/Darrell 2305/2303 Blade roads 28 yds rock, 120M, | 27 |
| 14 yds oil sand | |
| 03/11/20 Nolan/Dayten 2501/2511/ Patch 2 yds oil 22A | |
| Myrtle Springs Sand | |
| 03/11/20 Bill/Woody 2120/2138/2119 Patched 3 ½ yds oil 24 | |
| 03/11/20 Bill/ Woody 2120/2138/2119 Tatched 3 72 yds oil 24 Kevin 2414/2115/2146 sand | |
| 03/11/20 Kenny/Darrell 2146 Blade road 63 yds of 120H, | 28 |
| Blade fold of yes of 12011, millings 27 | 20, |
| 03/12/20 Bill/Mike 2711/2703/2704 Patched 3 yds oil 22 | |
| 2721/2702 sand | |
| 03/12/20 Kevin 2112/2140/2146 Patch 3 yds oil 24 | |
| 2128/2144/2219 sand | |
| 2326 | |
| 03/13/20 Mike Worked in yard Case | |
| pushing up loader | |
| material | |
| 03/13/20 Bill/Nolan 2205/2200/ Clean ditch 1 yd oil Haultr | uck |
| 2307/2317/2318 and patched sand backho | |
| 27,22 | 1 |
| 03/13/20 Kevin/Dayten 2201/2206/2318 Patch 3 yds oil 24 | |
| 2214/2205 sand | |
| 03/16/20 Nolan/Woody 2708/2718/2914 Patch, cut tree 2 yds oil 22A | |
| 2915 2916 sand | |
| 03/16/20 Mike Worked in yard, Case | |
| push up backho | oe - |
| material 2016/2013/2700 B | |
| 03/16/20 Bill/Kevin 2916/2813/2708 Put up crime 2 yds oil 24 | |
| 2816/2718/2512 watch signs, sand | |
| 2534/2120/2105 patch | |
| 2514/2504/2503 2502 | |
| 03/17/20 Mike/Darrell 2901 Blade road 35 yds rock Case | |
| os/17/20 Mike/Darien 2901 Blade road 35 yds rock Case and milling backho | ne. |
| mixed, 1 yd 22, 28 | |
| oil sand 120M | , |
| 03/17/20 Bill/Kevin 2704 Clean ditch Mr. Gable Gradal | 1. |
| Nolan out took the dirt 23, 27 | 7 |
| 03/17/20 Woody, 2702/2431/2704 Patch 2 yds oil 22A | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

Date Employee County Roads Work Done Material Equip Used Dayten sand Myrtle Springs 03/18/20 Nolan/Woody Patch, 2146 2 yds oil 22A 2410/2144/2139 2112 sand Bill/Kevin/ 3 yds oil 03/18/20 2802/2801/2804 Patch, sink 24, haul Kenny 2816/2808/2807 hole on 2518. sand truck. 2803/2411/2414 backhoe cut tree on 2518 2501 03/18/20 Dayten/Mike 2918/2916/2903 Patched 3 yds oil 22 2912/2909/2310 sand, cut 2501 tree 2501 03/19/20 Nolen/Woody 2808/2141/2145 Patch 22A 2 yds oil 2120 sand Bill/Kevin 2 yds oil 03/19/20 2111/2120/2411 Patched/ 24 sand, 1 yd 2112/2506/2507 milling on 2508/2509/ millings mail boxes 03/19/20 Dayten/Mike 2404/2504/2507 Patched 4 yds oil 22 2434/2306/2405 sand 2512/2510/2433 2316 03/20/20 Kenny/Darrell Checked roads 20B 03/20/20 Nolan 2816 Patched Put up 22A bridge reflectors, 1 yd oil sand 03/20/20 Put up safety Mike 2900/2800/2700 22 2300/2500 barrels. repaired washout 2300's 03/20/20 Bill/Kevin 1 yds oil 24 2100's/2500's Patched, cut tree 2512 sand Nolan/Woody 2 yds oil 03/23/20 2816/2139/2144 Patched 22A 2120 sand Kevin/Dayten 2412/2418/2620 3 yds oil 24 03/23/20 Patched 2602 sand 21 vds 03/23/20 Bill/Mike 2507/2316/2317 Filled in cave Haul ins and tank millings, 21 truck, 26, car failure yds rip-rap backhoe Bill/Mike 2315/2705/2721 Added rock to Haultruck 03/24/20 14 vds rock, 3 yds oil 2718/2703/2704 road Backhoe, shoulders sand 26, 24 2315, patched Kevin/Dayten 2600's Patched 4 yds oil 24 03/24/20 sand

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-------------------------------------|----------------------------------|--|-----------------------------------|--------------------------------------|
| | T | - 10 | | . | |
| 03/24/20 | Nolan/Woody | 2808/2809/2915 2914 | Patched | 2 yds oil sand | 22A |
| 03/25/20 | Darrell/Mike Nolan | 2141 | Strip patched | 49 yds oil sand | 120M, 28, 27 |
| 03/25/20 | Nolan/Woody | 2402/2424/2404 | Patched | 2 yds oil sand | 22A |
| 03/25/20 | Bill/Kevin | 2716/2721/2806 2807/2141 | Patched worked on bridge, ditch work 2806 | 21 yds oil sand, 1 yd patch | Gradall, 23, 22 |
| 03/26/20 | Nolan/Mike | 2138/2144/2506 2507 | Patch | 2 yds oil sand | 24 |
| 03/26/20 | Bill/Mike | 2315/2316/2313 | Cleaned ditch 2319, repaired culvert 2316, | | Backhoe, 26 |
| 03/26/20 | Kevin | 2319/2316/2802 2808/2621/2622 | Patched | 3 yds oil sand | 22 |
| 03/27/20 | Kevin/Dayten | 2518/2701 | Patched | 1 yd oil sand | 24 |
| 03/27/20 | Bill/Mike Nolan | 2141 | Installed 15x30 culvert, cleaned out ditch | 14 yds rock | Haul truck, backhoe, 26, 27 |
| 03/30/20 | Bill/Kevin | 2319/2316/2313 2518/2414/2516 | Picked up oil sand Malakoff, patched | 3 yds oil sand | 26, 22 |
| 03/30/20 | Mike/Dayten | Worked in shop | | | 120H |
| 03/30/20 | Nolan/Woody | 2421/2147/2201 2205/ | Patched | 2 yds oil sand | 22A |
| 03/31/20 | Bill/Woody Kevin/Nolan Dayten | 2507/2813/2810 2802 | Cut up tree on 2507, patched | 1 yd oil sand | 24, haultruck backhoe, 25 |
| 03/31/20 | Kevin | 2700's | Patched | 1 yd oil sand | 22 |
| 04/01/20 | Nolan/woody | 2205/2804/2816 | Patched | 2 yds oil sand | 22 |
| 04/01/20 | Mike/Kevin | 2503/2506 | Cleaned out cross rd pipe 2503, repaired wing on bridge 2506 | 14 yds rock | Backhoe, haultruck 23 |
| 04/02/20 | Mike/Nolan | 2501 | Repaired base | 42 yds | Case |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|-------------|------------------|-------------------------|--------------------|-----------------|-------------------|
| | T | - 11 | • | | 1 |
| | | | failures | crushed | backhoe, |
| 0.440.545.0 | | | | concrete | 23,27 |
| 04/02/20 | Bill/Darrell | 2908/2802/2313 | Repaired cave | 14 yds rip | Gradall, |
| | | 2311/2312 | in 2908, | rap, 3 yds | 26, 24 |
| | | | patched | oil sand, 1 | |
| | | | | yd oil sand | |
| 04/02/20 | Davitas / | 2802/2816/2918 | Patched | patch 2 yds oil | 22A |
| 04/02/20 | Dayten/ Woody | 2916/2912/2313 | Fatched | sand | ZZA |
| | Woody | 2304/2306/2307 | | Sand | |
| | | 2416/2705/2903 | | | |
| 04/03/20 | Bill/Nolan | 2629/2621/2625 | Patched | 3 yds oil | 24 |
| 0 1/ 03/ 20 | Dili/T (Oldi) | 2631/2512/2404 | 1 dicirca | sand | |
| 04/03/20 | Dayten/Nolan | 2326/2510 | Patched | 1 yd oil | 24 |
| | , | | | sand | |
| 04/03/20 | Kevin/Bill | Patched picked | | 1 yd oil | 22 |
| | | up tires | | sand | |
| 04/03/20 | Mike/Kevin | Worked in | | | |
| | Dayten | shop, on | | | |
| | | equipment | | | |
| 04/06/20 | Mike/Bill | 2913 | Installed | 14 yds oil | 23, 26, |
| | | | 18x24 | sand, 14 yds | case |
| | | | driveway | concrete | backhoe |
| 04/06/20 | NT - 1 | D11 41- | culvert | | |
| 04/06/20 | Nolan | Packed trash, worked on | | | |
| | | equipment | | | |
| 04/06/20 | Woody/Nolan | 2434/2435/2511 | Patched | 3 yds oil | 22A |
| 0-7/00/20 | Woody/140iaii | 2434/2433/2311 | 1 atelied | sand | 2211 |
| 04/06/20 | Bill/Kevin | 2504 | Patched | 1 yd oil | 24 |
| 0 1, 00, 20 | | | | sand | |
| 04/07/20 | Mike/Bill | 2401/2139/2322 | Repair cross | 14 yds oil | Case |
| | Darrell/Nolan | 2319 | pipe, 2401, | sand, 1 yd | backhoe, |
| | | | 2139, patched | patch truck | 26, 27, 22 |
| | | | 2322, 2319 | | |
| 04/07/20 | Kevin/Woody | 2309/2322/2900 | Patched | 3 yds oil | 24 |
| | | 's | | sand | |
| 04/07/20 | Dayten/Nolan | 2309/2307/2303 | Patched | 4 yds oil | 22A |
| 04/00/20 | D:11/17 ' | 2307/2409/2511 | D1 1 2004 | sand | 12074.27 |
| 04/08/20 | Bill/Kevin | 2901, cherry | Blade 2901 | 70 yds | 120M, 27, |
| | Mike/Darrell | Ck. | with concrete, | concrete, 49 | 23, 28 |
| | | | strip patched | yds Dmix | |
| | | | Cherry Ck oil sand | | |
| | | l | Saliu | | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|-----------|--------------------|---------------------|------------------------|-------------------|------------------------|
| | T | - 12 | • | | |
| 04/08/20 | Woody | 2304/2208/2205 | Patched | 2 yds oil | 22 |
| | | 2200/2414/2602 | | sand | |
| 0.4/00/20 | Mai /Dai | 2120/2112 | D : 11 | 40 1 | |
| 04/09/20 | Mike/Bill | 2414 | Repaired base failures | 49 yds | Case |
| | Kevin/Nolan | | lanures | concrete | backhoe, 26, 23, 27 |
| 04/09/20 | Kevin 4 hrs | 2311/2310 | Patched | ½ yd oil | 22 |
| 04/07/20 | Kevin + ins | 2311/2310 | 1 atched | sand | |
| 04/13/20 | Nolan | 2801/2418/2431 | Patched | 1 ½ yds oil | 22A |
| | | | | sand | |
| 04/13/20 | Kevin/Woody | 2100's/2804 | Patched, cave | 3 yds oil | 22 |
| | | 2801/2205/2202 | ins | sand | |
| 04/13/20 | Bill/Nolan | 2602/2217/2301 | Cut tree 2602, | 3 yds oil | 24 |
| | Mike | 2411/2507/2506 | patched | sand | |
| 04/14/20 | Woody | 2716/2708/2711 | Patched | 2 yds oil | 22A |
| | | 2710/2721/2718 | | sand | |
| | | 2715/2705 | | | |
| 04/14/20 | Bill/Keivn | 2147 | Blade road | 35 yds of | 120H, 26, |
| 04/14/20 | Mike | 0.600/0514/0147 | D1 1 1 | rock | 23 |
| 04/14/20 | Mike/Bill Kevin | 2602/2514/2147 | Blade roads | 70 yds rock, | 120H, 23, 26 |
| | Keviii | | | 5 yds millings | 20 |
| 04/15/20 | Darrell/Nolan | 2602 | Blade road | 42 yds | 27, 120H |
| 0 1/13/20 | Darren, Tolan | 2002 | Diade foud | concrete | 27, 12011 |
| 04/15/20 | Woody | 2708/2721/2705 | Patched/ 1 yd | 1 yd | 22A |
| | | 2706/2702/2805 | on mail boxes | millings, 2 | |
| | | 2816/2802 | | yds oil sand | |
| 04/16/20 | Darrell/Nolan | 2211/2602 | Patched/blade | 35 yds crush | 27/120H, |
| | | | 2211 | concrete, 1 | |
| | | | | yd oil sand | |
| 04/16/20 | Bill/Kevin | 2602/2620 | Blade roads | 28 yds rock, | 120H, 26, |
| | Mike | | | 35 yds of | 23 |
| | | | | crush | |
| 04/17/20 | Mike | 2311/2410/2620 | Patched | concrete | 22 |
| 04/17/20 | IVIIKC | 2311/2410/2020 | 1 attricu | 1 yd oil sand | |
| 04/17/20 | Mike/Bill/ | 2620/2129 | Blade roads | 7 yds crush | 120H, 23, |
| 0 1/11/20 | Kevin/ | 2020,2127 | 2100010000 | concrete | 26 |
| 04/17/20 | Nolan/Darrell | 2414 | Installed | 14 yds rock | 23, case |
| | | | 12x24 culvert | , | backhoe |
| 04/17/20 | Bill/Kevin | 2313/2802/2703 | Patched | 1 yd oil | 24 |
| | | 2816 | | sand | |
| 04/20/20 | Kevin/Woody | 2602/2147/2513 | Patched | 1 yd oil | 22 |
| | | 2512/2412/2410 | | sand | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|-----------------|-----------------|---|----------------|---------------|-------------------|
| | T | - 13 | 5 - | Т | Т |
| 2 4 / 2 2 / 2 2 | | 2418 | | | |
| 04/20/20 | Mike/Bill | 2403/2808 | Clean ditch | 4 yds rock, | 26, 25, 28 |
| | Kevin/Darrell | | out, cut trees | 7 yds rip rap | case |
| | | | | | backhoe |
| 04/21/20 | Mike/Bill | 2808/2806/2801 | Cleaned out | 7 yds | Case |
| | Nolan | | ditch 2808, | crushed | backhoe, |
| | | | 2806, repaired | concrete | 27, 26, 28 |
| | | | base failures | | |
| | | | 2801 | | |
| 04/21/20 | Kevin/Woody | 2501/2301/2507 | 2300's, | 3 yds oil | 22 |
| | | 2914/2915/2916 | patched | sand | |
| 04/22/20 | Mike/Nolan | 2808/2801 | Repaired base | 21 yds crush | 120M, 28, |
| | Darrell | | failures | concrete, 7 | 27 |
| | | | | yds old mix | |
| 04/22/20 | Bill/Kevin | 2317/2806/2808 | Patched | 3 yds oil | 26 |
| | | 2801/2319/2316 | | sand | |
| | | 2317 | | | |
| 04/23/20 | Nolan/Darrell | 2428/2432/2501 | Blade roads, | 49 yds | 27, 120M |
| | | 2908 | cut tree, | concrete, 1 | |
| | | | patched | yd oil sand | |
| 04/23/20 | Mike/Bill/ | 2801 | Repaired base | 42 yds crush | Case |
| | Kevin | | failures | concrete | backhoe, |
| 0.1/0.1/0.0 | | • | | 40 1 | 23, 26 |
| 04/24/20 | Bill/Kevin | 2801 | Repaired base | 49 yds crush | 23, 26, |
| 0.4/0.4/0.0 | Mike | 2410/2402/2504 | failures | concrete | backhoe |
| 04/24/20 | Nolan/Woody | 2410/2403/2506 | Patched | 2 yds oil | 22A |
| | | 2317/2806/2801 | | sand | |
| 04/27/20 | Bill/Mike | 2601 | Repaired base | 35 yds crush | 26, 27, |
| | Nolan | | failures | concrete | case |
| 0.4/07/00 | XX 1 /C 1 | 2412/2400/2504 | D . 1 1 | 2 1 11 | backhoe |
| 04/27/20 | Woody/Grady | 2413/2409/2504 | Patched | 2 yds oil | 22A |
| | | 2506/2806/2807 | | sand | |
| 0.4/20/20 | N. 1 0.1 | 2808/2103/2120 | D . 1 . 1 | 4 1 11 | 2.4 |
| 04/28/20 | Nolan 3 hrs | 2421/2437 | Patched | 1 yd oil | 24 |
| 0.4/20/20 | W 1 /C 1 | 0.40.4/0.400/0.410 | D . 1 1 | sand | 22.4 |
| 04/28/20 | Woody/Grady | 2424/2402/2412 | Patched | 2 yds oil | 22A |
| | | 2101/2105/2102 | | sand | |
| | | 2109/2518/2521 | | | |
| 04/29/20 | Milro/Dill | 2514/2420 | Domlogad | 21vd ma ala | 22 26 27 |
| 04/28/20 | Mike/Bill | 2316 | Replaced | 21yd rock | 23, 26, 27 |
| | Kevin/Nolan | | cross road | | case backhoe |
| | Darrell | | culvert, | | backnoe |
| | | | 18x40, clean | | |
| | | | ditches | | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|--------------------------|---|--|--|------------------------------|
| | T | - 14 | | | |
| 04/29/20 | Woody/Grady | 2200/2202/2139 2144/2124/2112 2140/2116/2146 2621/2129 | Patched | 2 yds oil sand | 22A |
| 04/29/20 | Nolan/Darrell | 2602/2721/2112 2404/2409 | Patched, cut tree, rock to driveways | 1 yd oil sand, 7 yds rock | 24, 27, t- rex backhoe |
| 04/29/20 | Bill/Kevin Mike | 2316 | Repaired base failures | 49 yds crush concrete | Case backhoe, 26, 23 |
| 04/30/20 | Bill/Nolan | 2436/2725 | Installed 15x24, patch | 14 yds rock, 1 yd oil sand | Trex, 24 |
| 04/30/20 | Mike/Kevin/ Bill | 2316/2301 | Repaired base failures | 35 yds crush concrete | Case backhoe, 26, 23 |
| 05/01/20 | Mike/Bill Kevin/Nolan | 2301/2303 | Installed 2 driveway pipes, 2303, 15x30 and 15x24, repaired base failures on 2301 | 35 yds rock, 21 yds crush concrete | 27, 26, 23, case backhoe |
| 05/01/20 | Darrell | 2902 | Blade road, put up PR 6290 | Sign/post | 120M |
| 05/04/20 | Bill/Kevin Mike | 2301 | Repaired base failures | 35 yds crush concrete | Case backhoe, 28, 23 |
| 05/04/20 | Woody | 2304/2306/2310 2311 | Patched | 2 yds oil sand | 22 |
| 05/05/20 | Bill/Mike Kevin | 2301/2314 | Repaired base failures 2301, installed 15x24 culvert on 2314 | 35 yds crush concrete, 14 yds rock | Case backhoe, 23, 28 |
| 05/05/20 | Ferrell | 2622/2623/2624 | Blade roads | | 120H |
| 05/05/20 | Nolan/Darrell | 2205/2504 | Repaired ditch and fixed pipe | 7 ½ yd oil sand, 1 bag of concrete | 120M, 27, 22A |
| 05/05/20 | Cody/Grady | 2721/2705/2112 | Patched | 5 yds oil sand | 24 |
| 05/06/20 | Bill/Mike | 2414/2306/2415 | Repaired base | 7 yds crush | Case |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|----------------------------|---|---|--|----------------------------|
| | 1 | - 15 | | | T |
| | | | failures, clean ditch installed 12x30 drway culvert on 2306 | concrete, 28 yds rock | backhoe, 26 |
| 05/06/20 | Ferrell, Nolan Darrell | 2623/2621 | Blade roads | 2623, 28 yds millings, 35 yds rock 2621 | 120H, 27, 23 |
| 05/06/20 | Cody/Woody | 2705/2112/2504 2708 | Patched | 5 yds oil sand | 24 |
| 05/07/20 | Woody | 2708/2711/2719 | Patched | 3 yds oil sand | 22A |
| 05/07/20 | Mike/Bill Kevin/Darrell | 2805 | Strip patched road | 5 flowboys, 123 tons of wood county oil sand | 120M, 23, 26, 28 |
| 05/07/20 | Cody/Grady | 2415/2427/2414 2403/2912/2301 2416/2302 | Patched | 6 yds oil sand | 24 |
| 05/07/20 | Ferrell/Nolan | 2128 | Blade road | 35 yds crush concrete | 120H, 27 |
| 05/08/20 | Kevin/Nolan Grady | 2206/2205/2501 2115/2721 | Patched, repaired sign 2721 | 2 yds oil sand | 22 |
| 05/08/20 | Grady | 2807/2806/2801 2809 | Patched | 2 yds oil sand | 22A |
| 05/08/20 | Bill | 2411/2413/2310 | Patched, worked in shop | 1 yd oil sand | 24 |
| 05/08/20 | Bill/Mike | 2708/2721 | Cleaned ditch 2708, hauled two cross rd culverts 2708 | 3 ½ yds oil sand | Case backhoe, 26 |
| 05/11/20 | Woody | 2405/2509/2504 2505/2503/2502 2511/2411 | Patched | 3 yds oil sand | 22A |
| 05/11/20 | Kevin/Mike Bill | 2708 | Installed two crossroad culverts, 15x30 and 24x40 | 28 yds crush concrete | Case backhoe, 23, 26 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|---------------------|---|---|--|---|
| | | - 10 | • | | |
| 05/11/20 | Nolan/Ferrell | 2140/2406/2601 | Blade roads | 35 yds crush concrete | 27, 120H |
| 05/11/20 | Cody/Grady | 2804/2426/2414 | Patch | 3 yds millings, 4 yds oil sand | 24 |
| 05/12/20 | Woody | 2511/2521/2519 2534/2501/2520 | Patched | 3 yds oil sand | 22A |
| 05/12/20 | Nolan/Ferrell | 2409/2406 | Blade roads | 35 yds rock, 14 yds millings | 27 |
| 05/12/20 | Cody/Grady | 2429/2401/2411 2434/2404 | Patched | 5 yds oil sand | 24 |
| 05/12/20 | Bill/Mike Kevin | 2804/2807 | Repaired base failures | 42 yds crush concrete | Case backhoe, 26, 23 |
| 05/13/20 | Bill/Mike/ Kevin | 2807 | Repaired base failures | 49 yds crush concrete | Case backhoe, 26, 23 |
| 05/13/20 | Nolan/Ferrell | 2708/2713 | Blade roads | 49 yds crush concrete | 120H, 27 |
| 05/13/20 | Woody/Grady | 2534/2434/2437 /2421/2407 2404 | Patched, picked up stolen signs from 2410 | 3 yds oil sand | 24 |
| 05/14/20 | Nolan/Ferrell | 2708/2724 | Blade roads | 42 yds crush concrete | 27 |
| 05/14/20 | Cody/Grady | 2718/2719/2114 2417/2910/ orzaka road | Patched | 4 yds oil sand | 24 |
| 05/14/20 | Bill/Mike Kevin | 2807/2802 | Repaired base failures | 49 yds crush concrete | Case backhoe, 26, 232 |
| 05/15/20 | Nolan/Darrell | 2407/2710/2508 | Patch, installed 15x30 culvert 2426 | 14 yds rock, 1 yd millings | 22A, 27, terex backhoe |
| 05/15/20 | Bill/Mike Kevin | 2209/2207 | Installed dr way culvert, 15x24, 2209 cleaned out round rock bed | 7 yds 6'' rock, 14 yds crush concrete. | Case backhoe, 25, 26, 23 haultruck |
| 05/18/20 | Grady/Woody | 2501/2801/2435 2141/2519 | Patched, cut up tree | 2 yds oil sand | 24 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|------------------------|---|---|--|------------------------|
| | | - 17 | • | | |
| 05/18/20 | Nolan | 2318/2410 | Hauled rubble from bridge to barn 2318, patched 2410, stock piled concrete | ½ yd oil sand | 27, 22A |
| 05/18/20 | Bill/Mike Kevin | 2718 | Clearing road and ditches of tornado debris | 9 loads 63 yds of debris to barn | Case backhoe, 25 |
| 05/19/20 | Mike/Bill | 2318 | Hauled old oil sand from bridge 2318 | 56 yds to barn | 28 |
| 05/19/20 | Grady/Woody | 2219/2704/2708 2721 | Patched | 3 yds oil sand, 2yd millings | 24 |
| 05/19/20 | Bill/Nolan | 2718 | Cut tree off road from tornado | 42 yds brush | Case backhoe, 25 |
| 05/19/20 | Ferrell/Darrell | 2708 | Blade roads | 14 yds crush concrete | 120H, 26 |
| 05/20/20 | Cody/Grady | 2120/2102/2111 /3443/myrtle springs | Patched | 4 yds oil sand | 24 |
| 05/20/20 | Nolan/Ferrell | 2901/2315 | Blade roads | 49 yds crush concrete | 27, 120H |
| 05/20/20 | Woody | 2711/2707/2703 | Patched | 3 yds oil sand | 22A |
| 05/20/20 | Bill/Darrell | 2805 | Strip patched | 56 yds oil sand | 26. 120M |
| 05/20/20 | Mike/Kevin Bill | 2718/2719 | Cleaned up brush from tornado | 63 yds of brush | Casebackh oe, 25 |
| 05/21/20 | Cody/Grady | 2101/2102/ Mytle Springs, 2410/2405 | Patched | 5 yds oil sand | 24 |
| 05/21/20 | Nolan/Ferrell Kevin | 2501/2506 | Blade roads | 14 yds oil sand, 63 tons crushed concrete | 27, 26 |
| 05/21/20 | Darrell/Bill Mike | 2804 | Strip patched road | 91 yds oil sand | 120M, 28, 26 |
| 05/22/20 | Mike/Bill Kevin | 2901/2318 | Hauled beams to barn from | | Case backhoe, |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|------------------------|---------------------------------------|--|-------------------------------|------------------------|
| | T | - 18 | | ı | 1 |
| | | | bridge on 2318, cut up | | 25 |
| | | | trees | | |
| 05/22/20 | Kevin/ | 2506 | Patched | 1 yd oil sand | 24 |
| 05/22/20 | Nolan/Ferrell | 2506 | Blade road | 35 yds crush concrete | 27, 120H |
| 05/26/20 | Nolan | 2205/2120/2702 | Patched | 2 yds oil sand | 22A |
| 05/26/20 | Mike/Kevin | 2120 | Picked up tree brush, got tires put on 26, 23 | | 22, 26, 23 |
| 05/26/20 | Grady/Woody | 2702/2506/2309 | Patched | 4 yds oil sand | 24 |
| 05/27/20 | Woody | 2702 | Patched | 3 yds oil sand | 22 |
| 05/27/20 | Nolan/Kevin Ferrell | 2506 | Blade road | 35 yds crushed concrete | 27, 23, 120H |
| 05/27/20 | Cody/Grady | 2120/2117 | Patched | 5 yds oil sand | 24 |
| 05/27/20 | Bill/Mike Darrell | 2301 | Strip patched | 63 yds of oil sand | 120Mm 28m 26 |
| 05/27/20 | Nolan/Kevin Ferrell | 2405 | Blade road | 35 yds crushed concrete | 27, 23 |
| 05/28/20 | Woody | 2703/2702/2714 2707/2709 | Patched | 3 yds oil sand | 22 |
| 05/28/20 | Bill/Mike Darrell | 2301/2326 | Strip patched | 77 yds oil sand | 120M, 26, 28 |
| 05/29/20 | Grady | 2302 | Patched | 4 yds oil sand | 24 |
| 05/29/20 | Nolan/Ferrell Kevin | 2819/2820, purtis creek estates | Blade roads | 63 yds oil sand | 23,27 |
| 05/29/20 | Mike/Bill Darrell | 2301/2212/2317 | Strip patched | 56 yds oil sand | 28, 26, 120M |
| 06/01/20 | Bill/Kevin | 2705/2411 | Repaired hole 2705, cleaned up trash | 7 yds oil sand | Case backhoe, 23 |
| 06/01/20 | Mike/Darrell | Haul equipment to 2201 | | | |
| 06/01/20 | Woody | 2709/2702/2705 | Patch | 3 yds oil | 22 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

Date Employee County Roads Work Done Material Equip Used - 19 -2710 sand 06/02/20 Bill/Kevin 2420/2601 Repaired base 5 yds crush 24. case failures bachoe, 26 concrete Woody 2721 06/02/20 Patched 3 yds oil 22A sand 06/02/20 Cody/Grady 2205/2311/2312 Patched 5 yds oil 24, 22 2304/2313/2316 sand 06/02/20 Mike/Darrell 2201 Overlay road 14 120M, flowboys, rosco 350 tons of roller Wood County Dmix 06/03/20 Cody/Grady 2517/2516 Patched 5 yds oil 24 sand 06/03/20 Bill/Kevin 2601 Repaired base 28 yds Case bh, failures concrete 26 06/03/20 Nolan/Ferrell 2413/2819 Blade roads 63 vds crush 27, 120H concrete 06/03/20 Mike/Darrell 2204/2205 Overlay roads 10 120M, flowboys, rosco 250 tons roller wood county dmix 22A 06/03/20 Woody 2705/2706/2720 Patched 3 yds oil 2719/2719/2718 sand 2722/2723/2724 2715 6 yds oil 24 06/04/20 Cody/Grady 2816/2819/2813 Patched sand Worked in 06/04/20 Kevin shop, repaired mirror 23 06/05/20 Bill/Mike 77 yds oil 2520/2206/2205 Strip patched 120M, 26, Darrell sand 28 1 yd oil 22 06/05/20 Kevin 2808/2802 Patched sand Bill/Kevin Dug out old 10 yds 06/05/20 2808 Case culvert concrete backhoe, replaced 23 15x24 Cody/Grady Patched 4 yds oil 24 06/05/20 2811/2807/2813 sand 2511/2501/2517

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------------------|--|---|--|---|
| | 1 | - 20 | | I | |
| 06/05/20 | Nolan/Ferrell | 2413/2809 | Blade roads | 28 yds rock, 7 yds oil sand | 27 |
| 06/05/20 | Mike/Nolan Darrell | 2102/2120/2205 2801 | Strip patched, roads | 28 yds oil sand 1yd patch 2801 | 28, 120M, 20B, 21A |
| 06/08/20 | Kevin/Nolan Ferrell | 2418/2801 | Strip patched, 2801 | 77 yds oil sand | 24, 23, 27 120H |
| 06/08/20 | Woody | 2801/2804/2802 2816/2808/2815 2810/2807/2806 | Patched | 3 yds oil sand | 22 |
| 06/08/20 | Bill/Mike/ Darrell | 2120/2602 | On 2120 fixed Pete shoulder strip patched 2602 | 14 yds crush concerte, 42 yds oil sand | 120M, 26, 28 |
| 06/09/20 | Kevin/Ferrell Bill | 2801/2802/2808 | Strip patch | 77 yds oil sand d-mix | 120H, 23, 26 |
| 06/09/20 | Bill/Mike Darrell | 2602 | Strip patch | 54 yds oil sand using d-mix | 120M, 28, 26 |
| 06/09/20 | Grady/woody | 2318/2214/2221 2305/2202 | Patched | 4 yds oil sand | 24 |
| 06/10/20 | Woody | 2908/2902/2901 2912/2914/2915 2916/2819 | Patched | 2 yds oil sand | 22 |
| 06/10/20 | Bill/Ferrell | 2715 | Repaired base failures | 63 yds crush concrete | 120H, 26 |
| 06/10/20 | Cody/Grady | 2120/2121/2604 2602/Myrtle Springs/2141 | Patched | 4 yds oil sand | 24 |
| 06/10/20 | Mike | 2908 | Worked in yard | | |
| 06/11/20 | Bill/Mike/ Nolan/Stanley | 2908 | Installed 26x40 cross rd culvert | 21 yds rip rap, 21 yds concrete | Haultruck case backhoe, 26, 23, 27 |
| 06/11/20 | Cody/Grady | Myrtle Springs | Patched | 4 yds oil sand | 24 |
| 06/11/20 | Ferrell/Nolan | 2708 | Blade road | 14 yds crush concrete | 120H, 27 |
| 06/12/20 | Mike/Nolan | 2908, | Delivered pipe to 2908, installed electric motor | Nolan patched 2510, 2437, 1 yd oil | 22A, haul truck |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|------------|-----------------------|--|--|--|-----------------------------|
| | 1 | - 21 | | 1 | |
| | | | on air | sand | |
| 0.5/1.0/00 | G 1 | 0111101101010 | compresser | <i>z</i> 1 '1 | |
| 06/12/20 | Grady | 2114/2112/2120 | Patched | 6 yds oil sand | 24 |
| 06/15/20 | Woody/Jones | 2310/2311/2120 | Patched | 2 yds oil sand | 22 |
| 06/15/20 | Ferrell | 2708 | Blade road | | 120H |
| 06/15/20 | Bill/Kevin Stanley | 198/2410 | Set concrete culvert | 3 yds millings | SDLG, Gradall, 23, 27 |
| 06/16/20 | Darrell/Mike | 2316 | Overlay road | 14 flowboys, 336 tons of Woodcount y D-mix | 120M, rosco roller |
| 06/16/20 | Grady | 2112, Myrtle Springs | Patched | 3 yds oil sand | 24 |
| 06/16/20 | Jones/Stanley | 2426/2603/2426 | Worked on mowers, put up signs, on listed roads | | Mow truck |
| 06/16/20 | Nolan/Ferrell | 2420/2710 | Blade roads | 42 yds millings | 27, 120H |
| 06/16/20 | Woody | 2312/2313/2314 216/2319/2322 | Patched | 2 yds oil sand | 22 |
| 06/17/20 | Mike/Darrell | 2316 | Overlay road | 15 Flowboys, 360 tons of Wood County D- mix | 120H, rosco roller |
| 06/17/20 | Bill/Kevin | Haul tire to tyler, changed 120M tire, mow | | | |
| 06/17/20 | Woody | 2317/2318/2323 2200/2205/2214 2219/2213 | Patch | 2 yds oil sand | 22 |
| 06/17/20 | Grady | 2311/2312/2314 2322/ | Patched | 4 yds oil sand | 24 |
| 06/17/20 | Nolan/Ferrell | 2303/2305 | Blade roads | 49 yds crush concrete | 27, 120H |
| 06/17/20 | Mike J, Stanley | Worked on mowers | | | |
| 06/18/20 | Bill/Kevin | 2317/2718/2715 | Installed cross | 7 yds crush | Case |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|-------------|---------------------|---------------------|--------------------|----------------|-------------------|
| | T | - 22 | | T . | 1, ,, |
| | | 2705/2702/2703 | rd pipe, 15x30 | concrete | backhoe, |
| 06/10/20 | N-1/C1 | 2201/2410 | 2317, patched | 2 1 1 | 23, pt 23 |
| 06/18/20 | Nolan/Grady | 2301/2410 | Put up road | 2 yds oil sand | 24 |
| | | | signs 2710/2515/23 | Sand | |
| | | | 15/2603 patch | | |
| 06/18/20 | Mike/Darrell | 2316 | Overlay road | 10 | 120H, |
| 00/10/20 | Wirke, Darreit | 2310 | Overlay road | Flowboys, | rosco |
| | | | | 250 tons of | roller |
| | | | | Wood | |
| | | | | county D- | |
| | | | | Mix | |
| 06/18/20 | Mike J, | 2909/2404 | Worked on | 1 yd oil | 22 |
| | Stanley | | mowers and | sand | |
| | | | patched | | |
| 06/19/20 | Grady | 2316/2317 | Patched | 2 yds oil | 24 |
| | | | | sand | |
| 06/19/20 | Bill/Kevin | 2120/2307/2415 | Installed 2, | 42 yds rock | Case |
| | Stanley | | 12x24 | | Backhoe, |
| | | | culverts, and | | 23 26 |
| | | | 18x24 on 2120 | | |
| 06/19/20 | Nolan/Darrell | 2316/2804 | Strip patched | 35 yds d- | 120M, 27, |
| 00/19/20 | Mike | 2310/2004 | Surp paterieu | mix | 28 |
| 06/22/20 | Woody/Jones | 2800's | Mowing | IIIX | 20B, |
| 00/22/20 | Stanley | 2000 5 | 1,10 miles | | Kabotas |
| 06/22/20 | Mike/Devin | Worked in | | | |
| | | shop, changing | | | |
| | | oil in equipment | | | |
| 06/22/20 | Bill/Kevin | 2120/2627/2502 | Cleaned up | 1 yd oil | Haul 25 |
| | | 2503/2434/2410 | tree limbs, | sand | 24 truck, |
| | | | patched | | case |
| | | | | | backhoe, |
| 06/23/20 | Nolan | 2421/2410 | Patched | 2 yds oil | 21A |
| 0.5/0.5/0.5 | D 1 550 | G1 | | sand | |
| 06/23/20 | Devin/Mike | Changed oil in | | | |
| | | trucks and | | | |
| 06/22/20 | Ionas/Stanlari | equip | Movvina | | Valentes |
| 06/23/20 | Jones/Stanley | 2800's | Mowing | | Kabotas, 20B |
| 06/23/20 | Woody Bill/Kevin | 2511/2507/2506 | Cut brush and | 2 yds oil | 24 |
| 00/23/20 | DIII/Keviii | 2511/2307/2300 | patched | sand | ∠ -1 |
| 06/24/20 | Devin | Worked in shop | paterica | Sand | |
| 00/27/20 | DOVIII | on all | | | |
| | İ | JII all | <u> </u> | J | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

County Roads Date Employee Work Done Material Equip Used - 23 equipment, greased, etc 06/24/20 Darrell/Mike 2602/2316 Cut tree 2602, 6 flowboys, 120M, 144 tons of overlay 2316 rosco Wood roller County Dmix Grady Patched 3 yds oil 24 06/24/20 2120/2115/2502 2410/2419 sand Bill/Farrell 2804/2603 06/24/20 Strip patched 42 yds mix 120H, 26, Nolan on 2804, 35 28 yd mix on 2603 06/24/20 Jones/Woody 2812/2700's Mowing Kubotas, Stanley 20B 06/25/20 Grady/Stanley 2112/2120 Patched 3 yds oil 24 sand 22 06/25/20 Kevin/Woody 2812/2901 Put up signs 2 yds oil 2812 patched sand 06/25/20 Mike/Darrell 2316/2725/2719 Sign on 2725, 2 flowboys, 120M, Kevin overlay 2316, 40 tons of rosco, 22, tree down Wood casebackh 2719 county Doe mix Worked in shop 06/25/20 Devin 91 yds oil 06/25/20 Bill/Nolan 2603/2601 Strip patched 120H, 26, Ferrell 2603, and sand, 2602, 28 14 yds oil strip pached 2601 sand 2601 22 06/26/20 Nolan 2410/2507 Patch 1 yd oil sand 2700's 06/26/20 Woody/Jones Mowing Kubotas, Stanley 20B Mike/Devin 06/26/20 Worked in shop 2 yds oil 06/26/20 Bill/Kevin 2900's/2718 Patched 22 2311/2312 sand 2406/2401/2434 3 yds oil Cody/Grady 24 06/29/20 Patched 2506/2507 sand 1 yd millings 06/29/20 Devin/Mike Moved 2316/2317 Darrell equipment, serviced equipment Jones/Stanley 2700's 20B. 06/29/20 Mowing

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

County Roads Date **Employee Work Done Material Equip Used** - 24 -Woody kubotas 77 yds oil 06/29/20 Bill/Kevin 2604/2715/2506 Strip patched, 120h, 26, Nolan/Ferrell 2411/2402/2434 patched sand, 2604, 28, 23 2506 2715, 2 yds oils patch 3 yds oil 06/30/20 Grady 2410/2411/2511 Patched 24 2501/2502/2507 sand 2506/2510 06/30/20 Jones/Stanley 2702/2600's Mowing Kubotas, Woody 20B 10 Mike/Darrell 2317 Overlay road 120M, 06/30/20 flowboys, rosco 340 tons of roller Wood County dmix 06/30/20 Worked in shop Devin servicing vehs 06/30/20 Bill/Nolan 2715/2725 Strip patched 77 yds oil 120H, 26, sand, 14 vds Ferrell 28 millings 06/30/20 Kevin 2214/2219/2213 Boomaxe Boomaxe 07/01/20 Bill/Kevin 2213/2317/2210 1 yd oil Boomaxe, Boomaxe, 2209/2208 2213,2317 sand 22 patched 07/01/20 Devin Worked in shop cut tree 2808 07/01/20 Mike/Darrell 2317/2808 14 120m, Strip patch Devin 2317, tree on flowboys, rosco, 24 2808 336 tons of Wood County Dmix 3 yds oil 07/01/20 Grady 2716/2708/2721 Patched 24 2719 sand 07/01/20 Jones/Woody 2600's Kubotas, Mowing 20B Stanley 07/02/20 Jones/Woody 2600's Mowing Kutotas, 20B Stanley 07/02/20 Bill/Kevin 14 yds 2715/2404/2403 Strip patched, L120H, Ferrell 2715, patched millings, 63 26, 23, 22 yds oil sand 2715, 1 yd patch.

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|----------------------------|---|--|---|--|
| _ | | - 25 | 1 | | _ |
| 07/02/20 | Grady | 2144/2124/2128 2311 | Patched | 3 yds oil sand | 26 |
| 07/02/20 | Jones/Stanley Woody | 1600's | Mowing | | Kubotas, 20B |
| 07/02/20 | Mike/Devin Darrell | 2317 | Worked on equipment | | |
| 07/06/20 | Woody/Jones Stanley | 2600's/2100's | Mowing | | Kubotas, 20B |
| 07/06/20 | Bill/Kevin | 2313/2627 | Patched | 3 yds oil sand | 24 |
| 07/06/20 | Kenny/Devin | 2708/2716/2426 | Put up signs | St, yield, stop signs | 20R |
| 07/07/20 | Woody/Jones Stanley | 2100's | Mowing | | Kubotas, 20B |
| 07/07/20 | Bill/Kevin | 2702/2112/2146 2147/2128 | Patched, pick up brush, hot tub, patched | 2 yds oil sand | Case backhoe, 25, 24 |
| 07/07/20 | Kenny/Devin Mike | Worked in shop, repaired rosco, fix flats | | | |
| 07/08/20 | Bill/Kevin Devin | 2307/2808/2627 2629/2621/2624 | Patched cut up tree 2307/2308 | 2 yds oil sand | Case backhoe, 25, 22 |
| 07/08/20 | Devin/Kenny Mike | 2808/2708/2918 | Cut tree of 2808, boomase and blade 2708 | 56 yds crush concrete 2708 | Boomaxe, 28, 120H |
| 07/08/20 | Cody/grady | 2501/2507/2506 | 2511, patched | 4 yds oilsand | 24 |
| 07/08/20 | Woody/jones Stanley | 2100's | Mowing | | 20B, kubotas |
| 07/09/20 | Bill/Mike Kevin/Darrell | 2507 | Installed two 36x40 crossroad culverts | 21 yds riprap, 28 yds crush concrete | Caes backhoe, gradall, 27, 26, 27 |
| 07/09/20 | Cody/Grady | 2145/2112/2144 2137/2138 | Patch, pickup 6 tires 2144 | 4 yds oil sand | 24 |
| 07/09/20 | Woody/Jones Stanley | 2100's | Mowing | | Kubotas, 20B |
| 07/09/20 | Kenny/Darrell Devin | 2507/2708/2719 | Put up road signs, blade road, boomaxe 2708/2719 | 14 yds crush concrete | 120H, boomaxe, 27 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|------------------------|----------------|----------------|----------------|-------------------|
| 07/10/20 | Code/Casder | 2139/2144/2120 | 1 | 4 - 1 - 1 | 24 |
| 07/10/20 | Cody/Grady | 2139/2144/2120 | Patched | 4 yds oil sand | 24 |
| 07/10/20 | Bill/Kevin | 2507/2900's | Finished | 14 yds oil | Case |
| | | | culvert work | sand, 1 yd | backhoe, |
| | | | on 2507, | patch | 23, 22A |
| | | | patched | | |
| 07/10/20 | Kenny/Devin | 2719/2139/2301 | Boomaxe, | | Boomaxe, |
| | | | 2719, put up | | lawnmowe |
| | | | no thur truck | | r, 20R |
| | | | sign 2139, put | | |
| | | | up stop sign | | |
| | | | mowed yard | | |
| 07/10/20 | Stanley | 2621 | Patched | 4 yds oil | 22 |
| 0=110150 | | | | sand | 1 |
| 07/10/20 | Jones/Stanley | 3400's | Mowing | | Kubotas, 20B |
| 07/13/20 | Woody Bill/Kevin | 2301/2316/2307 | Patched | 2 vda oil | 24 |
| 07/13/20 | Dill/Kevili | 2305/2302/2120 | rattieu | 2 yds oil sand | 24 |
| | | 2101/2318 | | Sand | |
| 07/13/20 | Kenny/Mike | 2708/2721 | Boomaxe, set | | Water |
| 07/13/20 | Devin | 2700/2721 | up 2708 for | | truck, |
| | DO VIII | | overlay | | 120H, |
| | | | o verialy | | roller, |
| | | | | | Boomaxe |
| 07/14/20 | Kenny/Mike | 2708 | Overlay road | 15 | 120H, |
| | | | , | flowboys, | rosco |
| | | | | 355 tons of | roller |
| | | | | Wood | |
| | | | | county D- | |
| | | | | mix 2 in | |
| | | | | thick | |
| 07/14/20 | Jones/Stanley Grady | 2100's/2200's | Mowing | | Kubotas, 20B |
| 07/14/20 | Devin | 2719/2723/2724 | Boomaxe | | Boomaxe |
| 07/15/20 | Grady/Woody | 2311/2310/2326 | Patched | 4 yds oil | 22A |
| | | 2318 | | sand | |
| 07/15/20 | Kenny/Mike | 2708 | Overlay road | 15 | 120M, |
| | | | | flowboys, | Rosco |
| | | | | 354 tons of | roller |
| | | | | Wood | |
| | | | | county D- | |
| 07/15/20 | T /G: 1 | 21001 /22001 | 3.6 | mix | TZ 1 |
| 07/15/20 | Jones/Stanley | 2100's/2200's | Mowing | | Kubotas, |
| | Woody | | | | 20B |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads - 27 | | Material | Equip Used |
|----------|------------------------|--|--|--|----------------------------|
| 07/15/20 | Devin/Darrell | 2723 | Worked on steel wheel,move equipment | | 120H, roller, 23 |
| 07/15/20 | Bill/Kevin | Picked up voting boxes | | | |
| 07/16/20 | Devin | 2725/2715/2519 | Boomaxe | | Boomaxe |
| 07/16/20 | Kenny/Mike | 2708 | Overlay road | flowboys, 325 tons of Wood county D- mix | 120H, Rosco |
| 07/16/20 | Bill/Kevin | 2518/3440/3443 2802 | Pickup tires, installed 15x24 culvert repaired base failure 2802 | 14 yds rip rap, 28 yds crush concrete | Case backhoe, 24, 23 |
| 07/17/20 | Kenny/Devin Darrell | 2708/2723 | Overlay roads | flowboys, 250 tons of Wood county D- mix | 120H, Rosco |
| 07/17/20 | Bill/Kevin Stan | 2903/2318/2319 2900's | Patched | 2 yds oil sand | 24 |
| 07/20/20 | Bill/Kevin | 2803/2801/2802 2803 | Patch, installed cross rd.culvert 2803, 15x30 | 7 yds concrete, 1 yd oil sand | Case backhoe, 23, 22 |
| 07/20/20 | Kenny/Darrell Devin | 2723/2807 | Overlay roads | 8 flowboys, 2723, 7 flowboys 2807 of Texbit oil sand 375tons | 120H, 120M |
| 07/20/20 | Jones/Stan | Woody 2500's | Mowing | | Equip |
| 07/20/20 | Cody/Grady | 2903/2318/2319 2301/2308/2219 2213/2221/2217 | Patched | 5 yds oil sand | 24 |
| 07/21/20 | Jones/Woody Devin | 2500's | Mow | | Kubotas, 20B |
| 07/21/20 | Cody | 2105/2417 | Patched | 4yds oil san | 24 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------------------|-----------------------------|--|-------------------------------------|---|
| _ | 1 | - 28 | | <u> </u> | |
| 07/21/20 | Kenny/Darrell Mike/Kevin | 2312 | Cleaned ditches, | 14 yds dirt, 14 yds | 120M, backhoe, |
| | Bill | | installed 18x24 culvert | concrete | 25, 26, 28 |
| 07/22/20 | Jones/Stan Woody | 2500's | Mowing | | Kubotas, 20B |
| 07/22/20 | Bill/Kevin | 2901 | Patched, cleaned ditch out | 1 yd oil sand | Gradall, 23, 24 |
| 07/22/20 | Grady | 2813 | Patched | 3 yds oil sand | 22 |
| 07/22/20 | Devin | 2719/2807 | Boomaxe | | Boomaxe |
| 07/22/20 | Kenny/Mike | 2129 | Blade road | 42 yds crush concrete | 120H, 28 |
| 07/23/20 | Devin | 2808/2815/2807 | Boomaxe | | Boomaxe, 22 |
| 07/23/20 | Cody/Grady | 2816/2808/2810 2815 | patched | 5 yds oil sand | 24 |
| 07/24/20 | Kenny/Mike | 2601 | Blade road | 21 yds concrete | 120H, 28 |
| 07/24/20 | Bill/Kevin Mike/Kenny | 2518/2704/2702 | Clean out ditch, installed 15x24 culvert 2518 Patch 2704 2702 | 7 yds concrete, 1 yd oil sand | 120H, case backhoe, 23, 28 |
| 07/24/20 | Devin/Stanley | 2808/2815 | Boomaxe, patched roads | | Boomaxe, Kubota, 22 |
| 07/24/20 | Cody/Grady | 2719/2705/2721 | Patched, picked up tires | 4 yds oil sand | 24 |
| 07/27/20 | Bill/Kevin | 2604/2317/2318 2319/2309 | Moved equipment around, patched | 2 yds oil sand | 23, water truck, still roller, rent roller |
| 07/27/20 | Jones/Stan/ Woody | 2400's | Mowing | | 20B, kubotas, |
| 07/27/20 | Kenny/Mike Devin | 2601 | Set up road ro sealcoat, worked on boomaxe | 28 yds crush concrete | 120H, 28, water truck |
| 07/27/20 | Cody/Grady | 2719/2718 | Patch | 4 yds oil sand | 24 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used | | | |
|----------|-------------|---------------------|----------------|--------------|-------------------|--|--|--|
| - 29 - | | | | | | | | |
| 07/28/20 | Kenny/Mike | 2601/2430 | Set up for | 21 yds crush | 120H, rent | | | |
| | Devin | | sealcoat | concrete | roller, 28, | | | |
| | | | | | water | | | |
| | | | | | truck | | | |
| 07/28/20 | Cody | 2430/2431/2420 | Patched | 4 yds oil | 24 | | | |
| | | 2421/2705/2721 | | sand | | | | |
| | | 2716/2708/2725 | | | | | | |
| 07/28/20 | Bill/Kevin | 2413/2410/2508 | 2413 ready to | 28 yds crush | 120M, 26, | | | |
| | Darrell | 2507/2502/2503 | seal coat, | concrete, 2 | 23, 22 | | | |
| | | 2434 | patched | yds oil sand | | | | |
| 07/28/20 | Jones/Stan, | 2400's | Mowing | | Kubotas, | | | |
| | woody | | | | 20B | | | |
| 07/29/20 | Kenny/Mike | 2701/2602/2430 | Setting up | 42 yds crush | 120H, | | | |
| | | | roads for seal | concrete | water | | | |
| | | | coat | | truck, 28 | | | |
| 07/29/20 | Cody/Grady | 2410/2414/2411 | Patch | 4 yds oil | 24 | | | |
| | | | | sand | | | | |
| 07/29/20 | Bill/Kevin | 2430/2704/2703 | Installed | 7 yds crush | Haultruck | | | |
| | | 2701/2702 | 15x30 culvert | concrete, 2 | Case | | | |
| | | | 2704, patched | yds oil sand | backhoe, | | | |
| | | | | | 23, 22 | | | |
| 07/29/20 | Stan/Jones | 2400's | Mowing | | Kubota's, | | | |
| | Woody | | | | 20B | | | |
| 07/29/20 | Devin/Stan | Worked on | | | Power | | | |
| | | batwings | | | washer, | | | |
| | | mowers and | | | tools | | | |
| | | equipment | | | | | | |
| 07/30/20 | Devin | 2120 | Worked in | | Boomaxe | | | |
| | | | shop, | | | | | |
| | | | boomaxe | | | | | |
| 07/30/20 | Jones/Woody | 2400's | Mowing | | Kubotas, | | | |
| | | | | | 20B | | | |
| 07/30/20 | Grady/Stan | 2415 | Patched | 5 yds oil | 22 | | | |
| | | | | sand | | | | |
| 07/30/20 | Bill/Kevin | 2602 | Repair | 119 yds | 23,26 | | | |
| | | | | Rrap | | | | |
| 07/30/20 | Kenny/Mike | 2701/2406 | Blade roads | 63 yds crush | 120H, 28 | | | |
| | | | | concrete | | | | |
| 07/31/20 | Bill/Stan | 2602/2126/2624 | Blade roads, | 21 yds rip | Case | | | |
| | | | hauled trash | rap, | backhoe, | | | |
| | | | to dump, trim | | 26, 23, 25 | | | |
| | | | trees | | | | | |
| 07/31/20 | Kenny/Mike | 2406/2717 | Blade roads | 21 yds | 120H, 28, | | | |
| | | | | concrete | SDLG | | | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------|---------------------------|-------------------|--------------------|-------------------|
| | | - 30 | • | | |
| 07/31/20 | Grady | 2418/2310 | Patched | 4 yds oil sand | 24 |
| 07/31/20 | Devin | 2120 | Boomaxe | | Boomaxe |
| 08/03/20 | Darrell/Devin | 2413 | Set up road | | 120M, |
| | | | for seal coat | | roller, |
| | | | | | water |
| 00/00/00 | | | | | truck |
| 08/03/20 | Bill/Kevin | 2413/2101/2120 | Patched | 3 yds oil | Haul |
| | | Cherry Ck, 2512 | moved | sand | truck, 22A |
| 08/03/20 | Woody | 2710/2704/2703 | equipment Patched | 2 yds oil | 22 |
| | , | | | sand | |
| 08/03/20 | Jones/Stan | 2410/2416 | Mowing | | Kubotas, 20B |
| 08/03/20 | Kenny/Mike | 2313/2318 | Blade road | 14 yds oil sand | 120H, 28 |
| 08/04/20 | Woody/Jones | 2100's | | | Kubotas, |
| | - | | | | 20B |
| 08/04/20 | Bill/Kevin | 2701/2703 | Getting roads | | Haultruck |
| | | | ready for Seal | | 23, 24 |
| 00/04/20 | 5 /6 1 | 2210 | coat | | |
| 08/04/20 | Ray/Grady | 2319 | Patched | 4 yds oil sand | 22 |
| 08/04/20 | Kenny/Mike | 2701/2717 | Bladed roads, | 7 yds crush | 120H, |
| | Devin | | ready for seal | concrete, | steel |
| | | | coat | | wheel, |
| 08/05/20 | Stan | Workinghon | | | rosco |
| 08/05/20 | Devin | Work in shop Shop/2701 | Worked on | | Water |
| 06/03/20 | Deviii | Shop/2701 | mowers, | | truck |
| | | | water truck on | | HUCK |
| | | | 2701 | | |
| 08/05/20 | Bill/Kevin | 2144/2501/2502 | Installed | 21 yds rip | Case |
| | | 2503/2703 | 15x24 culvert, | rap, 7 yds C | backhoe, |
| | | | 2144, patched | concrete | 23, 26 |
| 08/05/20 | Kenny/Mike | 2701 | Getting road | | Gradall, |
| | | | ready for seal | | gackhoe, |
| | | | coat | | 25, water |
| 08/05/20 | Grady | 2704/2705/2706 | Patched | 4 yds oil | truck 24 |
| | , | | | sand | |
| 08/05/20 | Jones/Stan | 2200's/2300's | Mowing | | Kubotas, |
| 00/05/25 | Woody | 2515/2511/252 | | 4 1 | 20B |
| 08/06/20 | Bill/Kevin | 2717/2711/2708 | Equipment to | 1 yd oil | 26, 24, |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------------------|---------------------------------------|--|--------------------------------------|---------------------------------------|
| | 1 | - 31 | | T | 1 |
| | | 2721 | 2717/ patched | sand | case backhoe |
| 08/06/20 | Jones/Ray Woody | 2300's | Mowing | | Kubotas, 20B |
| 08/06/20 | Kenny/Mike Devin | 2701/2717 | Blade water road, ready to seal coat | 42 yds crush concrete | 120H, water truck, rollers |
| 08/07/20 | Bill/Kevin Stan | 2703 | Installed 18x40 cross road culvert | 14 yds rip rap, 7 yds concrete | Backhoe, 26, 27 |
| 08/07/20 | Kenny/Mike Devin | Worked in shop on all equipment | | | Re claimer, 28 |
| 08/10/20 | Chase/Grady | 2205/2706/2434 2401/2414 | Patched | 4 yds oil sand | 22 |
| 08/10/20 | Jones/Stan Woody | 2300's | Mowing | | 20B, kubotas |
| 08/10/20 | Bill/Kevin | 2128/2909/2914 2915 | Moved equip, patched | 2 yds oil sand | 26, 22A |
| 08/10/20 | Kenny/Devin Mike | 2128 | Blade/ boomaxe | | 120H, rollers, water truck |
| 08/11/20 | Grady/Chase | 2602 | Patched | 4 yds oil sand | 22 |
| 08/11/20 | Mike/Kevin | 2427/2300's | Installed 15x24 driveway culvert 2427, patch | 14 yds rip rap, 7 yds concrete | Case backhoe, 26, 22 |
| 08/11/20 | Kenny/Mike Devin/Darrell | 2128 | Set up road for sealcoat | 6 yds oil sand | 120H, Wt Rollers, re claimer 27 |
| 08/11/20 | Jones/Stan Woody | 2300's | Mowing | | 20B, Kubotas |
| 08/12/20 | Grady/Chase | 2121/2403/ 2120 | Cut weeds in ditch at bridge patched | 3 yds oil sand | 22A |
| 08/12/20 | Jones/Stan Woody | 2300's | Mowing | | 20B, Kubotas |
| 08/12/20 | Kenny/Mike Devin/Darrell | 2128 | Road ready for seal coat | 4 yds concrete | 120H, 28, m26 |
| 08/12/20 | Bill/Kevin | 2120/2112/2410 | Move crossrd | 2 yds oil | 24, haul |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used | | |
|----------|---------------------|---|---|---|--|--|--|
| r | - 32 - | | | | | | |
| | | 2404/2414 | pipe to 2120, patched | sand | truck | | |
| 08/13/20 | Jones/Stan | 2900's | Mowing | | 20B, | | |
| | Woody | | | | kubotas | | |
| 08/13/20 | Bill/Kiven | 2723/2715/2725 | Strip patched | 63 yds oil | 26, 23, | | |
| | Darrell | 2715/2723/2807 | and patched | sand, 1 yd oil sand | 22A, 120M | | |
| 00/12/20 | 77 /3 611 | 2120/2112 | D1 1 1 | patch | 10011 | | |
| 08/13/20 | Kenny/Mike Devin | 2128/2112 | Blade rock on 2128, strip patched 2112 | 42 yds concrete, 7 yds oil sand | 120H, roller, water truck, 28 | | |
| 08/13/20 | Grady | 2602/2112/2418 | Patched | 4 yds oil sand | 22 | | |
| 08/14/20 | Grady/Stan | 2128/2124/2134 | Patched | 3 yds oil sand | 22 | | |
| 08/14/20 | Bill/Kevin | 2602/2219/2209 2112/2120 | Moved equipment, patched | 2 yds oil sand | 22A, haul truck | | |
| 08/14/20 | Kenny/Mike Devin | 2112/2116 | Strip patched, worked on equipment | 14 yds oil sand | 120H, 28, boomaxe 24 | | |
| 08/17/20 | Grady/Chase | 2403/2310/2414 2428 | Patched | 4 yds oil sand | 24 | | |
| 08/17/20 | Mike/Darrell | 2101, cherry blossom, packed trash, worked in shop | | | Backhoe, 28, 27 | | |
| 08/17/20 | Jones/Stan Woody | 2900's | Mowing | | 20B, kubotas | | |
| 08/17/20 | Bill/Kevin | 2410/2100's 2500's/2800's | Cut tree up, patched | 1 yd oil sand | 25, backhoe, 22 | | |
| 08/17/20 | Kenny/Devin | Worked on Boomaxe, | And equipment | | Equip- ment | | |
| 08/18/20 | Grady/Chase | Myrtle Springs | Patch | 3 yds oil sand | 24 | | |
| 08/18/20 | Jones/Stan Woody | 2900's | Mowing | | Kubotas, 20B | | |
| 08/18/20 | Kenny/Mike Devin | 2601/2139 | Overlay 2601, repairing base failures on 2139 | Flowboys, 300 tons of TexBit dmix | 120H, 27, case loader | | |
| 08/18/20 | Bill/Kiven | 2120/2139 | Installed | 42 yds crush | | | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|---------------------|--|---|---------------------------|---------------------------------------|
| | 1 | - 33 | | Γ | |
| | Kenny/Darrell | | 36x36 cross rd culvert 2120, failures 2139 | concrete | truck, case backhoe, 23, 26, 27 |
| 08/19/20 | Darrell/Mike | Worked in shop | | | |
| 08/19/20 | Devin | Shop | Worked on SDLG loader, steel wheeler | | |
| 08/19/20 | Grady/chase | Myrtle springs | Patched | 3 yds oil sand | 24 |
| 08/19/20 | Jones/Stan Woody | 2800's | Mowing | | Kubotas, 20B |
| 08/19/20 | Kenny/Bill Kevin | 2139/2624 | Repaired base failures | 35 yds crush concrete | Backhoe, 23 26, case loader |
| 08/20/20 | Mike/Darrell | Work in shop and yard | | | |
| 08/20/20 | Grady | 2505/2520/2102 2101/2102/2311 2312 | Patched | 4 yds oil sand | 24 |
| 08/20/20 | Jones/Stan Woody | 2800's | Mowing | | 20B, kubotas |
| 08/20/20 | Kenny/bill Kevin | 2621 | Repaired base failures | 70 yds crush concrete | Case backhoe, 26, 23 |
| 08/20/20 | Devin | Worked in shop on SDLG loader and case loader | | | |
| 08/21/20 | Devin | Shop, worked on all equipment | | | |
| 08/21/20 | Bill/Kevin Mike | 2621/2721/2705 2310/2311 | Repaired base failues 2621 | 35 yds concrete 2OS | Backhoe, 23, 26 24 |
| 08/21/20 | Kenny/Darrell | 2916 | Put up roads signs | | 20C |
| 08/24/20 | Grady/Chase | 2916/2918 | Patch | 4 yds oil sand | 24 |
| 08/24/20 | Bill/Kevin | 2701/2139/2713 2705/2702 | Cut tree limb 2701 patched | 2 yds oil sand | Case backhoe, 25, 22 |
| 08/24/20 | Jones/Woody | 2700's | Mowing | | 20B,Kbtas |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-------------------------|--|---|---|----------------------------|
| | | - 34 | | | |
| 08/24/20 | Kenny/Mike Devin/Ray | 2147 | Blade road getting ready to overlay, worked on | Skid plate for boomaxe | 20R, 120H, 2 backhoe |
| 00/00/00 | | | mowers | | |
| 08/25/20 | Grady/Chase | 2813 | Patch | 4 yds oil sand | 22 |
| 08/25/20 | Jones/Woody | 2700's | Mowing | | Kubotas, 20B |
| 08/25/20 | Devin/Kenny Mike | 2147/Devin worked on boomaxe | Overlay road | flowboys, 279 tons of Wood County Dmix | 120H, rent roller, 20B |
| 08/25/20 | Stan | 2801/2802 | Patched, cut log off road | 1 yd oil sand | 22A |
| 08/25/20 | Kevin/Bill | 2914/cherry cheek/2101/ 2120/2219/2326 2302/2309/2316 | Patched | 2 yds oil sand | 24 |
| 08/26/20 | Bill/Kevin | 2144/2512/2506 2120/2312/2311 2310 | Patched, speed limit 2144 | 2 yds oil sand | 24 |
| 08/26/20 | Kenny/Mike Devin | 2147 | Overlay road | 8 flowboys 186 tons of Wood County Dmix | 120H, 20R |
| 08/26/20 | Jones/Woody | 2700's/2600's | Mowing | | Kutota, 20B |
| 08/26/20 | Grady/Chase | 2813/2807 | Patched | 4 yds oil sand | 22 |
| 08/26/20 | Stan | 2802/2816/2808 2807/ | Patched | 3 yds oil sand | 22A |
| 08/27/20 | Jones/Woody | 2600's | Mowing | | 20B, kubotas |
| 08/27/20 | Grady/Chase | 2319 | Patch | 3yds oilsand | 24 |
| 08/27/20 | Bill/Kevin | 2916/2101 | Filled hole, installed culvert 15x24, 2120 | 28 yds rip rap, 7 yds oil sand | Case backhoe, 23 |
| 08/27/20 | Ray AKAstan | 2501/2301 | Put up sign 2501, | 2 yds oil sand, 1 sign, | 22 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

Date Employee County Roads Work Done Material Equip Used - 35 patched, 2301 bracket Kenny/Mike 08/27/20 2147 Blade 21 yds rock 120H, Devin southside, 120M 2147, equipment back to barn 08/28/20 Worked in Devin shop, 28, 120M 08/28/20 Kenny/Mike 2315 Blade road 126 yds 120H, 27, Ray concrete 28 Bill/Kevin Case 08/28/20 2602/2147/2426 Installed 7 vds 2512/2504 backhoe, 15x24 culvert concrete 2426, patched 23 Grady/Chase 2914/2120/ 3 yds oil 24 08/31/20 Patch cherry ck/2101 sand 08/31/20 Ray/Woody 2807/2804 Patched 2 yds oil 22 picked up sand trash 2804 Bill/Kevin Cherry ck/2143 Patched, 2 yds oil Case 08/31/20 2624/2627/2624 pickup tree sand backhoe, 2512 Cherry ck 25, 22A Kenny/Devin Worked in shop 08/31/20 Mike 3 yds oil 09/01/20 Ray/Woody 2807/2705/2129 Patched. 22A picked tires sand 09/01/20 Grady/Chase 2311/2309/2301 4 vds oil 24 Patched sand 3 yds oil 09/01/20 Bill/Kevin 3443/3442/3225 Patched 22 2624/2602 sand 09/01/20 Kenny/Darrell Worked in shop Mike/Devin on equipment, 120H, watertruck hose 09/02/20 Bill/Kevin 2135/2112/ Patched 22 2100's cleaned out barn Ray 24 09/02/20 Shop work 09/02/20 Kenny/Devin Worked on Shop Mike/Darrell 120H. backhoe 24 09/03/20 Bill/Kevin Bridges, Put up 20 2404/2504/2502 reflectors on reflectors, 1 /2511bridges, yd oil sand patched

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------|------------------------|-----------------|--------------|-------------------|
| | 1 | - 30 | • | | T |
| 09/03/20 | Kenny/Mike | 2322 | Cut tree off | | 20, 20r, |
| | Devin/Darrell | | road 2322, | | Backhoe |
| | | | pack trash, | | |
| | | | repaired | | |
| | | | mowtracktors | | |
| 09/03/20 | Ray | Worked in shop | | | |
| 09/04/20 | Woody | 2916/2903/2913 | Patched | 2 yds oil | 22A |
| | | 2313/ | | sand | |
| 09/04/20 | Devin/Ray | Shop, worked | | | |
| | | on equipment | | | |
| 09/04/20 | Grady/Chase | 2120/2511 | Patched | 3 yds oil | 24 |
| | | | | sand | |
| 09/04/20 | Kenny/Mike | 2128 | Blade road | 7 yds | 120H, 28, |
| | | | | concrete | SDLG |
| 09/08/20 | Devin | Shop, worked | | | |
| | | on Kubota | | | |
| 09/08/20 | Ray/Woody | 2120/2703 | Patched | 3 yds oil | 22A |
| 03/00/20 | Tay Woody | 2120/2703 | 1 dicirca | sand | 2211 |
| 09/08/20 | Bill/Keivn | Cherry Creek | Strip patched | 35 yds oil | 26, 23, |
| 05/00/20 | Darrell | Cherry Creek | Strip pateried | sand | 120M |
| 09/08/20 | Grady/chase | 2307/2506/ | Patched | 4 yds oil | 24 |
| 07/00/20 | Grady/chase | 2307/2300/ | 1 atched | sand | 24 |
| 09/08/20 | Kenny/Mike | 2128/2149 | Blade roads | 35 yds crush | 28, 120H |
| 09/08/20 | Kenny/wike | 2120/2149 | Diage Toaus | concrete | 20, 12011 |
| 09/09/20 | Devin | Worked in shop | | Concrete | |
| 09/09/20 | Devili | _ | | | |
| 00/00/20 | Bill/Kevin/ | on equipment 2120/2313 | Ctuin motals ad | 42 yds D- | 120M 24 |
| 09/09/20 | | | Strip patched | • | |
| | Darrell | Cherry creek | | mix, 1 yd | 26, 23, |
| 00/00/20 | C 1 /CI | 2120/2507 | D . 1 . 1 | oil sand | 24 |
| 09/09/20 | Grady/Chase | 2120/2507 | Patched | 4 yds oil | 24 |
| 00/00/20 | D / 1 | 2702/2702 | D . 1 . 1 | sand | 22.4 |
| 09/09/20 | Ray/woody | 2703/2702 | Patched | 3 yds oil | 22A |
| 00/00/00 | 77 2 71 | 2122/2122 | 5 | sand | 12077 20 |
| 09/09/20 | Kenny/Mike | 2129/2128 | Blade roads | 35 yds crush | 120H, 28 |
| | | | | concrete | |
| 09/10/20 | Grady/Chase | 2147/2534/2301 | Patch | 4 yds oil | 24 |
| | | | | sand | |
| 09/10/20 | Ray/woody | Worked in yard | | | |
| 09/10/20 | Bill/Kevin | 2102 | Cut up and | | |
| | Mike/Devin | | cleaned up | | |
| | Kenny/Darrell | | huge tree | | |
| 09/11/20 | Grady/Chase | 2306/2307 | Patch | 4 yds oil | 22 |
| | | | | sand | |
| 09/11/20 | Ray/Woody | Worked in shop | | | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|----------------------------|---|---------------------------------------|---|--|
| | | - 37 | | | |
| 09/11/20 | Bill/Kevin | 2804/2311/2312 2310/2313/2314 2315/2403 | Patch | 3 yds oil sand | 242 |
| 09/11/20 | Kenny/Mike Devin | 2401/2314 | Put up road signs | | 20R, case loader |
| 09/14/20 | Grady/Chase | 2102, cherry creek, college st 2120 | Patched | 3 yds oil sand | 22 |
| 09/14/20 | Devin | Shop | | | |
| 09/14/20 | Ray/woody | 2816/2801 | Patched | 2 yds oil sand | 24 |
| 09/14/20 | Bill/Kevin | 2309 | Installed 15x24 culvert, 2309 | 7 yd rip rap, 14 yds concrete | Haul truck, 27, 23, case backhoe |
| 09/14/20 | Kenny/Darrell Mike | 2506 | Strip patched | 4 flowboys, 200 tons of texbit d-mix | 120M 20R, roller 23 |
| 09/15/20 | Grady/Chase | 2147/2205/2120 | Patched | 4 yds oil sand | 24 |
| 09/15/20 | Woody | 2304/2801/2806 2802 | Patch | 3 yds oil sand | 22 |
| 09/15/20 | Devin/Darrell | 2517 | Strip patched road | 4 flowboys, 200 tons of texbit d-mix | 120M, rosco |
| 09/15/20 | Bill/Kevin | Hauled scrap iron | | | |
| 09/15/20 | Kenny/mike Ray | 2623 | Blade road | 70 yds of concrete millings | 120H, 26 ,27 |
| 09/16/20 | Grady/Chase | 2521/2520/2102 | Patching | 4 yds oil sand | 24 |
| | Darrell/devin KennyBill | | Strip patche strip patched road | 84 yds oil 84 84 yds oil sands 1 yd concrete | SDLG, reclaimer 120M 21,25, 28sdlg |
| 09/16/20 | Woody | 2304/2307/2309 | Patched | 3 yds oilsand | 22 |
| 09/16/20 | Kenny/mike Ray | 2623/2622 | Blade road | 77 yds crush concrete | 120H, 28, 27 |
| 09/17/20 | Grady/chase | 2601/2603/2620 | Patching | 3 yds oil sand | 24 |
| 09/17/20 | Devin | 2513 | Get equip | inspected | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|-----------------|-----------------|---------------------|----------------|--------------|--|
| | | - 38 | • | | , |
| 09/17/20 | Bill/Kevin | 2513/2514 | Strip patched | 72 yds | 120M, 26, |
| | Darell | | with concrete | concrete | 23 |
| 09/17/20 | Kenny/Mike | 2628 | Blade road | 77 yds | 120H, 27, |
| | Ray | | | concrete | 28 |
| 09/18/20 | Bill/Kevin | 2307/2627/2513 | Cut tree on | 2 yds oil | Case |
| | Darrell/Devin/ | 2703/2704/ | 2307, patched | sand | backhoe, |
| | Ray | | | | 25, STLG, |
| 0.5 / 1.0 / 5.0 | | | | | 20 |
| 09/18/20 | Kenny/Mike | 2621/2622 | Blade road | 21 yds | 120H, 28 |
| | | | | concrete, 6 | |
| 00/21/20 | D 0 14 | 2442/2545/2524 | G 1 G 11 | yds oil sand | 7076 |
| 09/21/20 | D & M | 2413/2717/2701 | Seal Coat all | \$162,057.50 | D&M |
| | contractors | 2604/2602/2601 | Roads | on Asphalt | equip. |
| 00/21/20 | D /W/ 1 | 2430/ | D . 1 | AC-5 | 24 |
| 09/21/20 | Ray/Woody | 2410 | Patch | 1 yd oil | 24 |
| 00/21/20 | D : | 2200 | D | sand | D |
| 09/21/20 | Devin | 2308 | Boomaxe | 1.4 1 | Boomaxe |
| 09/21/20 | Bill/Kevin | 2608 | Installed | 14 yds | Haultruck |
| | | | 12x24 culvert | concrete | case |
| | | | | | backhoe, 23 |
| 09/21/20 | Kenny/Mike | 2622/2621 | Blade roads | 35 yds crush | 120H, 26 |
| 09/21/20 | Keility/Wirke | 2022/2021 | Diade Toads | concrete | 12011, 20 |
| 09/21/20 | Darrell | 2434/2205 | Posted bridge | 2 post, 3 | 20 |
| 07/21/20 | Darren | 2+3+/2203 | load signs and | signs | 20 |
| | | | other signs | 515115 | |
| 09/22/20 | Devin/Darrell | 2719 | Boomaxe | | |
| 09/22/20 | Kevin/Bill | 2504/2404/2507 | Patched | 3 yds oil | 22 |
| 077 = 27 = 0 | | 2511/2534/2115 | | sand | |
| 09/22/20 | Ray/Woody | 2900's | Patch, cut | 1 yd oil snd | 24 |
| | | | brush | | |
| 09/22/20 | Kenny/Mike | 2719/2708 | Reclaiming | 1 yd | 22A, case |
| | | | oil sand | | loader, |
| | | | | | reclaimer |
| 09/23/20 | Grady/Chase | Myrtle Springs | Patch | 3 yds oil | 24 |
| | | | | sand | <u> </u> |
| 09/23/20 | Ray/Woody | 2702/2721/2703 | Patched | 3 yds oil | 22A |
| | _ | 2716 | | sand | |
| 09/23/20 | Devin | 2708/2705 | Boomaxe | | Boomaxe |
| 09/23/20 | Bill/Kevin | 2710/2708/2719 | Patched | 3 yds oil | 22 |
| | | 2403/2802/2806 | | sand | |
| | | 2808 | | | |
| 09/23/20 | Kenny/Mike | 2318 | Reclaimed oil | One no | Reclaimer |
| | Darrell | | mix | playing sign | 20,case 1 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|------------|-------------------|-----------------------------|--------------------|--------------------|-------------------|
| | T | - 39 | | Γ | T |
| 09/24/20 | Bill/Keivn | 2318 | Repaired base | 72 yds crush | |
| | Mike | | failures | concrete | truck, case |
| | | | | | backhoe, |
| 00/24/20 | Crady/Chaga | Myutla annings | Patch | 2 v.da oi1 | 23, 28 |
| 09/24/20 | Grady/Chase | Myrtle springs | Patch | 3 yds oil sand | 24 |
| 09/24/20 | Devin/Kenny | 2801/2804 | Boomaxe | | Boomaxe |
| 09/24/20 | Ray/Woody | 2909/2912/2313 2302 | Patch | 3 yds oil sand | 22 |
| 09/25/20 | Grady/Chase | 2112/2144/2128 | Patch | 3 yds oil sand | 24 |
| 09/25/20 | Kenny/Bill | 2801/2710/2120 | Cut up and | 28 yds | Boomaxe, |
| | Devin | 2502/2141 | hauled brush, | concrete | 25, 26, 22 |
| | | | blade road, | 2710, 7 yds | |
| | | | blade road, | oil sand | |
| | | | boomaxed, | | |
| 00/05/00 | D | 2410/2211/2000 | patched | 1 1 '1 | 22.4 |
| 09/25/20 | Ray | 2410/2311/2808 2410/2310 | mowed, | 1 yds oil sand | 22A, Kubota |
| | | 2410/2310 | patched | Sanu | mower |
| 09/25/20 | Mike | 2801/2205 | Hauled off | | 25, haul |
| 05/120/120 | 1 Trans | 2001/2200 | brush, | | truck |
| | | | boomaxe to | | |
| | | | 2205 | | |
| 09/28/20 | Grady/Chase | 2112/2146/2318 | Patched | 4 yds oil | 24 |
| | | /2311 | | sand | |
| 09/28/20 | Ray/Woody | 2120 | Patched | 2 ½ yds oil | 22 |
| | | | | sand | |
| 09/28/20 | Bill/Kevin | 2301/2319/2410 | Checked | 16 | 22A |
| 00/00/00 | D ' | /2621/2708 | bridges, repair | delineators | D |
| 09/28/20 | Devin Vanny/Miles | 2120/2112 | Boomaxe | 42 vda | Boomaxe |
| 09/28/20 | Kenny/Mike | 2303/2305 | Blade roads | 42 yds concrete | 120M, 26 |
| 09/29/20 | Ray | 2621/2624/2711 | Patched | 1 yds oil | 22 |
| | | 2705 | | sand | |
| 09/29/20 | Devin | 2120 | Boomaxe | | Booaxe |
| 09/29/20 | Bill/Kevin | 2708/2801/2918 | Worked on | 14 yds rip | 22A, 23, |
| | | | bridges per Txdot. | rap | 25 |
| 09/29/20 | Kenny/Mike | 2305/2922 | Blade roads, | 30 yds | 120M, 26, |
| | Darrell | | work in barn | concrete/mil | lawn |
| 00/22/2 | | | yard | lings | mower |
| 09/29/20 | Grady/Chase | 2219/2620/2406 | Patched | 3 yds oil | 24 |
| | | 2703 | | sand | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------|-----------------------------|---|--|---|
| | 1 | - 40 | | T | , |
| 09/30/20 | Ray/woody | Fairview, mid point, 2600's | Patched | 2 yds oil sand | 22 |
| 09/30/20 | Devin | 2120/2147/2148 | Boomaxe | | Boomaxe |
| 09/30/20 | Bill/Kevin | 2301/2918/2916 | Patched, dug | 2 yds oil | Backhoe, |
| | | 2309/2305/2314 | out culvert on 2301 | sand | 28, 22 |
| 09/30/20 | Grady/Chase | 2119/2116/2146 | Patch | 3 yds oil sand | 24 |
| 09/30/20 | Kenny/Mike | 2124/2140 | Repaired intersection, blade road | 14 yds oil sand, 14 yds millings | 120H, 26 |
| 10/01/20 | Grady/Chase | 2146/2112/2124 /2128 | Patch | 3 yds oil sand | 24 |
| 10/01/20 | Devin | 2147 | Boomaxe | | Boomaxe |
| 10/01/20 | Ray/Woody | 2602, toon town, 2147 | Patch, pick up tires | 2 yds oil sand | 22 |
| 10/01/20 | Bill/Kevin | 2414/2112/2114 | Patched, cut tree up | 1 yd oil sand | 25, caseback hoe |
| 10/01/20 | Kenny/Mike | 2128 | Ready for seal coat | | 120H, watertruck roller |
| 10/02/20 | Bill/Kevin | 2601 | Strip patched | 32 yds oil | 120M, 26, |
| | Kenny | | intersection | sand | 23 |
| 10/02/20 | Devin | Worked in shop | | | |
| 10/05/20 | Grady/Chase | 2112/2116/2146 | Patching | 3 yds oil sand | 24 |
| 10/05/20 | Ray/woody | 2627 | Patched | 3 yds oil sand | 22 |
| 10/05/20 | Bill/Kevin | 2708/2433/2508 | Cleaned out ditches, cross rd pipes | | Haultruck backhoe, 23 |
| 10/05/20 | Kenny/Devin | 2128 | Blade and rolled out road | | 120H, roller, water truck case loader |
| 10/06/20 | Grady/Chase | 2138/2114/2124 | Patched | 3 yds oil sand | 24 |
| 10/06/20 | Kenny/Darell | 2115 | Moved equipment to road, cleaned out ditch, pile crush concrete | | Case backhoe, 120M roller |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------------|---------------------|-----------------------------|-------------------------|-------------------|
| | T | - 41 | | | 1 |
| 10/06/20 | Mike/Kevin | 2404/2404 | Cut tree and | | Boomaxe, |
| | Ray/Woody | | brush away | | case |
| | Devin | | from bridges | | backhoe, |
| | | | cleaned out | | 25, 22 |
| 10/07/20 | 17. | 2405 | ditches | | D |
| 10/07/20 | Kevin | 2405 | Boomaxe | 2 1 11 | Booaxe |
| 10/07/20 | Ray/Woody | 3224/3449/2410 | Patch | 3 yds oil sand | 22 |
| 10/07/20 | Bill/Kevin | 2322/2317/2410 | Replaced stop | 14 yds crush | Case |
| | | 2305/2304/2309 | sign and road | concrete | backhoe, |
| | | 2317/2316 | sign at 2322/ | | 23 23 |
| | | | 2318/ 2317 | | |
| | | | installed | | |
| | | | 15x24 culvert, | | |
| 10/07/20 | Vanny/Milra | 2115/2139 | patched | 9 Flourbour | 120M, |
| 10/07/20 | Kenny/Mike Darrell | 2113/2139 | Overlay roads (strip patch) | 8 Flowboys, 200 tons of | rosco |
| | Danen | | (surp paten) | TexBit d- | roller |
| | | | | mix | Toner |
| 10/08/20 | Devin | 2405 | Boomaxe | IIIIX | Boomaxe |
| 10/08/20 | Ray/Woody | 2534 | Patched | 4 yds oil | 22/23 |
| 10/00/20 | itay/ Woody | 2331 | Tuteried | sand | 22/23 |
| 10/08/20 | Bill/Kevin | 2601 | Installed | 7 yds crush | Haultruck, |
| | | | 18x30 culvert, | concrete | case |
| | | | picked up 2 | | bachoe, |
| | | | loads of cold | | 26, 23 |
| | | | mix | | |
| 10/08/20 | Grady/Chase | 2624/2120/2102 | Patching | 3 yds oil | 24 |
| | | Cherry ck | | sand | |
| 10/08/20 | Kenny/Darrell | 2120/2139 | Overlay roads | 4 flowboys, | 120M, |
| | Mike | | (strip patched) | 200 tons of | rosco |
| | | | | TexBit d- | roller, 28 |
| | | | | mix | |
| 10/09/20 | Ray | 2115 | Patched | 1 yd oil | 22 |
| 10/05/25 | | | | sand | |
| 10/09/20 | Bill/Kevin | Changed tires | | | |
| | | out on 24 and | | | |
| 10/00/20 | Dani | big loader | | | |
| 10/09/20 | Devin | Shop, replaced | | | |
| | | brakes on 20B, | | | |
| | | worked on | | | |
| 10/00/20 | Vanny/Damali | boomaxe | Dut out aires | Ciona | 20P |
| 10/09/20 | Kenny/Darrell | 2120/2110 | Put out signs, fixed tolet | Signs, | 20R |
| | Mike | | nixeu totet | brckets, post | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

Date **Employee County Roads Work Done Material Equip Used** - 42 -10/13/20 Devin 2506 Boomaxe Boomaxe 10/13/20 Grady/Chase 2719/2721/2807 Patched 3 yds oil 24 sand Ray/Woody 1 yd oil 10/13/20 2115/2101 Patched, cut 22, chain brush 2101. sand saw cleared tree from bridge, picked up tires Bill/Kevin Steel wheel to 10/13/20 2128/2315/2802 1 yd oil Case backhoe, 2808/2807 yard, put road sand number signs 23, haul up, patched, truck clean cross rd pipe Blade road 10/13/20 Mike/Kenny 2128/2602 42 yds crush 120H, 26 concrete 10/14/20 Grady/Chase 2712/2901 Patching/ 3 yds oil 24 picked up sand tires 2605 Boomaxe 10/14/20 Devin Boomaxe 2 yds oil Ray/Woody 2318 Patch/ pickup 22, 20B 10/14/20 trash2901 sand Bill/Keivn 2901/2925 42 vds 10/14/20 Strip patch 120M, 26, millings, 14 Darrell 2901, blade 23, 22 2925, patch vds d-mix, 1 yd oil sand Kenny/Mike 10/14/20 Blade road 35 yds crush 120H, 26 2602 concrete Ray/Woody 22 10/15/20 Patched 3 yds oil 2802/2808/2915 sand 3 yds oil 10/15/20 Grady/Chase 2901/2102 Patched 24 sand 10/15/20 Devin 2405 Boomaxe Boomaxe 3 yds oil 20/15/20 Bill/Kevin 2112/2139/2144 Patched, 26, 23, 22 2517/2518/2519 picked up oil sand sand Malakoff 10/15/20 Kenny/Darrell 2219 Overlay road, 9 flowboys, 120M Mike strip patch 225 tons of Tex-bit dmix 10/16/20 Kevin/Bill 2309/2326/2318 Patched 2 yds oil 24 2903 sand Mike/Kevin 1 yd oilsand 22 10/16/20 2910/2802/2816 2924, patch

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------------|----------------------------------|---|--|--|
| | _ | - 43 | | | |
| 10/16/20 | Kenny/Mike | 2722/2721 | Blade roads | 21 yds millings | 120M, 27 |
| 10/16/20 | Grady/Chase | 2219/2317/2326 | Patching | 3 yds oil sand | 24 |
| 10/16/20 | Ray/Devin | 2138 | Picked up trash, worked shop | | 20R |
| 10/19/20 | Ray/Woody | 2102/2101/ MillCreek | Patch | 3 yds oil sand | 22 |
| 10/19/20 | Devin | 2326 | Boomaxe | | Kubota Boomaxe |
| 10/19/20 | Chase | 2411/2414/2427 2602 | Patch | 3 yds oil sand | 24 |
| 10/19/20 | Bill/Kevin | 2627 | Installed two 12x24 driveway culverts | 21 yds crush concrete | Haul truck, case back hoe, 22, 26 |
| 10/19/20 | Kenny/Mike | 2620/2318 | Blade roads, move equipment to 2318 ready for overlay | 28 yds millings | 120M, roller, 120H, 27, backhoe |
| 10/20/20 | Grady/Chase | 2434/2505/2112 2120/2416 | Patch | 3 yds oil sand | 22A |
| 10/20/20 | Devin | Shop, worked on 22, 24, | | | Shop tools |
| 10/20/20 | Ray/Woody | 2400's | Mowing | | Kubotas, 20B |
| 10/20/20 | Bill/Kevin | 2704/2703/2721 2702/2719/2718 | Patched, pick up 20 tons of oil sand in Malakoff. | 3 yds oil sand | 23, 26, 22, 24 |
| 10/20/20 | Kenny/Mike Darrell | 2318 | Overlay road | 15 Flowboys, 375 tons of Wood County oil sand | 120M, rosco roller |
| 10/21/20 | Grady/Chase | 2507/2505 | Patch | 3 yds oil sand | 24 |
| 10/21/20 | Ray/Woody | 2802/2815/2806 2803 | Mowing | | Kubotas, 20B |
| 10/21/20 | Kenny/Mike | 2144/2505 | Repaired base failures | 12 yds oil sand, 7yd R | 120H, 27 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-------------------|---------------------|----------------|--------------|-------------------|
| | T | - 44 | 1 | T | |
| | Darrell | 2205 | Put up road | 35MPH, | 20 |
| 10/21/20 | | | signs | curve sign, | |
| | | | | post | |
| 1021/20 | Bill/Kevin | 2704/2212/2434 | Strip patch | 10 yds oil | Case |
| | | 2306/2405 | 2704, and | sand, 2 yds | backhoe, |
| | | | patched | oil sand | 23 26, 22 |
| | | | | patched | |
| 10/22/20 | Grady | 2301/2120/2505 | Patched | 3 yds oil | 24 |
| | | 2506 | | sand | |
| 10/22/20 | Ray/Woody | 2819/2813/2812 | Mowing | | Kubotas, |
| | Devin | 2719/2708 | | | 20B |
| 10/22/20 | Bill/Kevin | 2101/Lakewood | Patching | 3 yds oil | 22 |
| | | Cherry ck, | | sand | |
| | | cherry blossom | | | |
| 10/22/20 | Kenny/Mike | Cherry creek/ | Mowed | | Little |
| | | 2520/2102 | ditches, creek | | Kubota |
| | | | on Cherry ck | | |
| 10/23/20 | Devin | Worked on big | | | |
| | | loader, mow | | | |
| | | tractors | | | |
| 10/23/20 | Bill/Kevin | 2142/2516/2518 | Put up signs/ | Signs, | 22 |
| | | 2403//2403/ | and patched | brackets, | |
| | | 2507/2516 | | post, 2 yds | |
| 10/20/20 | 77 (2.51) | ** 1 1 | 77 1 . 1 . 1 | oil sand | 77 1 |
| 10/23/20 | Kenny/Mike | Hauled mow | Kubota broke | | Haultruck |
| 10/05/00 | D : /D | tractor to Deens | down. | | |
| 10/26/20 | Devin/Ray | Shop, worked | | | |
| | | on little Kubota, | | | |
| | D . | repaired tail | | | |
| | Rain | wheel on | | | |
| 10/26/20 | D'11/IZ | mower | D . 1 | 2 1 | 22 |
| 10/26/20 | Bill/Keivn | 2704/2702/2403 | Patch | 2 yds | 22 |
| 10/26/20 | Mike | 2431/2436 | | millings | |
| 10/26/20 | Kenny/Darrell | Packed trash, | | | |
| | Mike | worked on | | | |
| 10/27/20 | Rain | backhoe | Class 1 | TT1 1' · · · | C 1 11 |
| 10/27/20 | Bill/Kevin | 2313/2702 | Cleaned out | Haul dirt to | Gradall, |
| 10/27/20 | Ray | 2206 | road ditchs | barn | 23, 26 |
| 10/27/20 | Devin Vanny/Milsa | 2306 | Boomaxe | | Boomaxe |
| 10/27/20 | Kenny/Mike | Worked in shop | | | 120H |
| | | on 120H, | | | grader |
| | | changed filters | | | |
| 10/29/20 | D;11/V av: | greased | Eill abouldess | Millings | 22 |
| 10/28/20 | Bill/Kevin | Mail boxes | Fill shoulders | Millings | 22 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| 10/28/20 Mike/Devin 2602/2702 Cut brush back from roads 20R, chain saw 10/29/20 Devin/Mike 2306/2307 Boomaxe Boomaxe 10/29/20 Ray/Woody 2700's/2306 Milling on mailboxes, brush on 2306 10/29/20 Bill/Kevin Check roads Milling on mailboxes Millings on mailboxes 10/29/20 Kenny/Darrell Raining, check roads Millings on mailboxes 10/29/20 Kenny/Darrell Raining, check roads Millings on mailboxes 10/30/20 Woody 2600's/2700's Milling on mailbox 20C Millings on mailbox Syds Millings on mailbox 10/30/20 Woody 2600's/2700's Millings on mailbox 10/30/20 Syds 22 10/30/20 Woody 2600's/2700's Millings on mailbox 10/30/20 Syds 22 10/30/20 Syds 22 10/30/20 Syds 22 10/30/20 Syds 3 10/30/20 Syds 3 10/30/20 Syds 3 10/30/20 Syds 3 10/30/30 Syds 3 10/3 |
|--|
| back from roads 10/29/20 Devin/Mike 2306/2307 Boomaxe Boomaxe 10/29/20 Ray/Woody 2700's/2306 Milling on mailboxes, brush on 2306 10/29/20 Bill/Kevin Check roads Milling on mailboxes millings 10/29/20 Kenny/Darrell Raining, check roads Millings on mailboxes 10/30/20 Woody 2600's/2700's Milling on mailbox millings 22 Millings on mailboxes 10/30/20 Woody 2600's/2700's Milling on mailbox millings |
| 10/29/20 Devin/Mike 2306/2307 Boomaxe Boomaxe |
| 10/29/20 Devin/Mike 2306/2307 Boomaxe Boomaxe 10/29/20 Ray/Woody 2700's/2306 Milling on mailboxes, brush on 2306 2 yds millings 10/29/20 Bill/Kevin Check roads Milling on mailboxes 2 yds millings 10/29/20 Kenny/Darrell Raining, check roads Millings on mailboxes 20C 10/30/20 Woody 2600's/2700's 2431/2436 Milling on mailbox 3 yds millings 22 |
| 10/29/20Ray/Woody2700's/2306Milling on mailboxes, brush on 23062 yds millings10/29/20Bill/KevinCheck roadsMilling on mailboxes2 yds millings10/29/20Kenny/Darrell Raining, check roadsMillings on mailboxes20C10/30/20Woody2600's/2700's 2431/2436Milling on mailbox3 yds millings |
| mailboxes, brush on 2306 10/29/20 Bill/Kevin Check roads Milling on mailboxes millings 10/29/20 Kenny/Darrell Raining, check mailboxes millings 10/29/20 Woody 2600's/2700's Milling on mailbox millings 20C 10/30/20 Woody 2600's/2700's Milling on mailbox millings |
| brush on 2306 10/29/20 Bill/Kevin Check roads Milling on mailboxes millings 10/29/20 Kenny/Darrell Raining, check roads Millings on mailboxes 10/30/20 Woody 2600's/2700's Milling on mailbox millings 20C 20C 23ds 2431/2436 Milling on mailbox millings |
| 10/29/20Bill/KevinCheck roadsMilling on mailboxes2 yds millings10/29/20Kenny/DarrellRaining, check roadsMillings on mailboxes20C10/30/20Woody2600's/2700's 2431/2436Milling on mailbox3 yds millings |
| mailboxes millings 10/29/20 Kenny/Darrell Raining, check millings on mailboxes 20C 10/30/20 Woody 2600's/2700's Milling on mailbox 3 yds 22 2431/2436 mailbox millings |
| 10/29/20Kenny/DarrellRaining, check roadsMillings on mailboxes20C10/30/20Woody2600's/2700's 2431/2436Milling on mailbox3 yds millings |
| roads mailboxes |
| 10/30/20 Woody 2600's/2700's Milling on a 3 yds 22 2431/2436 mailbox millings |
| 2431/2436 mailbox millings |
| |
| shoulders |
| |
| 10/30/20 Mike/Kevin 2431/2436 Blade roads 63 yds 120H, 27, |
| Kenny millings 23 |
| 10/30/20 Devin 2908 Boomaxe Boomaxe |
| 10/30/20 Kenny/Bill 2313 Cleaned out Halled dirt Gradall, |
| ditch to barn 27 |
| 11/02/20 Devin Worked on 22, |
| 24 changed all |
| filters in gas |
| pumps |
| 11/02/20 Bill/Mike/ 2211/2702/2802 Strip patched 77 yds crush 120H, 23, |
| Kenny 2211 and concrete, 1 26, 22 |
| 2702, patched yd oil sand |
| 2802 |
| 11/02/20 Ray/Woody 2916/2501/2511 Patched 2 yds oil 22/24 |
| sand |
| 11/02/20 Grady/Chase 2304/2334 Patched 2 yds oil 22A |
| sand |
| 11/03/20 Grady/Chase 2111 Patch 3 yds oil 22 |
| sand |
| 11/03/20 Devin/Mike 2318/2307 Overlay 2318, 13 flowboys 120H, |
| Darrell moved 354 tons of rosco, 20 |
| equipment to Wood |
| 2307 county oil |
| sand |
| 11/03/20 Ray 2802/2816/2807 Patched 2 yds oil 24 |
| 2140/2139 sand |
| 11/03/20 Bill/Kevin 2721/2705/2702 23, 26 to get 2 yds oil 23, 26, |
| inspected, sand 22A, 20B |
| patched |
| 11/04/20 Ray/Woody 2139/2512,2509 Patched 3 yd oilsand 22 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------------|---|---|--|--|
| | 1 | - 40 | • | ı | , , |
| 11/04/20 | Devin/Mike Darrell | 2307 | Strip patched | 5 flowboys, 125 tons of Wood County D- mix | 120M, rosco, 20B |
| 11/04/20 | Bill/Kevin | 2702 | Patched pickup voting boxes | 1 yd oil sand | 20R, 22A |
| 11/04/20 | Grady | Myrtle Springs | Patched | 2 yds oil sand | 24 |
| 11/05/20 | Devin | 2903 | Boomaxe | | Booaxe |
| 11/05/20 | Bill/Mike Kevin | 2434/2534 | Repaired Base failures | 63 yds crush concrete | Haul truck, case backhoe, 23,28 |
| 11/05/20 | Ray/Woody | 2101/2102/2423 2117/2120/2501 2101/2120 | Patched | 2 yds oil sand | 22 |
| 11/05/20 | Grady/Chase | Myrtle Springs | Patched | 3 yds oil sand | 24 |
| 11/06/20 | Bill/Mike/ Kevin | 2534/2405 | Repaired Base failures | 49 yds crush concrete | Case backhoe, 23, 28 |
| 11/06/20 | Ray/Woody | 2120/2145/2147 /2518/2403 | Patch | 3 yds oil sand | 22 |
| 11/06/20 | Devin | 2918 | Boomaxe | | Boomaxe, 20R |
| 11/06/20 | Grady/Chase | Myrtle Springs, 2120/2124/ | Patching | 3 yds oil sand | 24 |
| 11/09/20 | Chase | 2143/2145/2120 | Patch | 3 yds oil sand | 24 |
| 11/09/20 | Devin/Mike | Worked on Rosco Roller | | | |
| 11/09/20 | Bill/Kevin | 2918/2916 | Hauled new signal sign to barn from courthouse, patched | 1 ½ yd oil sand | 20R, 22 |
| 11/09/20 | Ray/Woody | 2903/2918/2209 | Hauled brush from 2903, patched | 2 yds oil sand | 22A |
| 11/10/20 | Grady/Chase | 2511/2502 | Patched | 3 yds oil sand | 24 |
| 11/10/20 | Bill/Kevin | Delivered air | Purifiers to | County | Offices |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-------------------------------------|--|---|-------------------------------------|--|
| | | - 47 | 7 - | | |
| 11/10/20 | Ray/Woody | 2807/2813/2812 | Patch | 3 yds oil sand | 22A |
| 11/10/20 | Devin/Mike | Worked on rosco roller, fixed gas pump | | | Shop tools |
| 11/12/20 | Chase/Grady | 2620/2120/2112 | Patch | 2 yds oil sand | 24 |
| 11/12/20 | Mike/Devin | Major overhall on Rosco Roller, | | | Shop tools |
| 11/12/20 | Kevin | 2300's | Milling on mailbox shoulders | 2 yds millings | 22 |
| 11/12/20 | Ray/Woody | 2800's/2700's | Milling on mailbox shoulders | 2 yds millings | 22A |
| 11/13/20 | Kevin/Ray | 2500's | Pickup d mix, packed trash, patched | 2 yds oil sand | Caseback hoe, 23, 22 |
| 11/13/20 | Grady | 2601/2602/2604 | Patched | 1 yd millings, 2 yds oil sand | 24 |
| 11/13/20 | Mike/Devin | Picked up two cargo trailers from topline trailer, worked on gradall | | | ³ / ₄ ton truck, 20R |
| 11/16/20 | Grady/Chase | 2620/2120 | Patched | 3 yds oil sand | 24 |
| 11/16/20 | Devin | 2308/Shop | Patched 2308, put hydraulic hose on backhoe | 1 yd oil sand | 20R |
| 11/16/20 | Bill/Kenny Mike/Kevin Darrell | 2308 | Installed 96x40 galvanized culvert (tank car) | 168 tons of oil dirt | Gradall, backhoe, haultruck, 23 26, 27, 28 |
| 11/16/20 | Ray/Woody | 2500's/2308/ 2426/2415/2412 | Patched | 2 yds oil sand | 22 |
| 11/17/20 | Grady/Chase | 2301/2302 | patched | 3 yds oil sand | 24 |
| 11/17/20 | Woody | 2412/2434/2502 2503/Tarva rd | Patched | 3 yds oil sand | 22 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| 11/17/20 |
|--|
| Mike/Ray Kevin car project, patched crush concret, millings, oil dirt case back hoe, 23 26, 27, 28 case big loader. 11/18/20 Grady/Chase 2303/2901/2120 Patching 3 yds oil sand 24 sand 11/18/20 Woody 2416/2410/2405 2434/2504/2509 Patch 2 ½ yds oil sand 22 sand 11/18/20 Devin/Kevin 2918/2916 Boomaxe Boomaxe 11/18/20 Bill/Mike 2901/2918 Blade road 77 tons 120M, 27, |
| Kevin |
| millings, oil dirt 26, 27, 28 dirt 26, 27, 28 dirt 26, 27, 28 dirt 26, 27, 28 dirt 27, 28 dirt 28, 27, 28 dirt 29, 27, 28 dirt 29, 27, 28 dirt 29, 27, 28 dirt 29, 27, 28 dirt 20, 27, 28 dirt 26, 27, 28 dirt 26, 27, 28 dirt 26, 27, 28 dirt 26, 27, 28 dirt 24, 28 dirt 24 dirt 25 dirt 24 dirt 24 dirt 24 dirt 25 dirt 25 dirt 25 dirt 26, 27, 28 dirt 27, 28 di |
| dirt case big loader. |
| 11/18/20 Grady/Chase 2303/2901/2120 Patching 3 yds oil sand 24 |
| 11/18/20 Grady/Chase 2303/2901/2120 Patching 3 yds oil sand 24 11/18/20 Woody 2416/2410/2405 Patch 2 ½ yds oil sand 22 11/18/20 Devin/Kevin 2918/2916 Boomaxe Boomaxe Boomaxe 11/18/20 Bill/Mike 2901/2918 Blade road 77 tons 120M, 27, |
| Sand Sand Sand |
| 2434/2504/2509 sand 11/18/20 Devin/Kevin 2918/2916 Boomaxe Boomaxe 11/18/20 Bill/Mike 2901/2918 Blade road 77 tons 120M, 27, |
| 11/18/20 Devin/Kevin 2918/2916 Boomaxe Boomaxe 11/18/20 Bill/Mike 2901/2918 Blade road 77 tons 120M, 27, |
| 11/18/20 Bill/Mike 2901/2918 Blade road 77 tons 120M, 27, |
| |
| |
| |
| equip 2918 concrete haultruck |
| 11/19/20 Grady/Chase 2311/2301/2511 Patched 3 yds oil 24 |
| sand |
| 11/19/20 Woody 2400's 2434/ Patched 1 yd 22 |
| 2410/2403/2415 millings, 2 |
| yds oilsand |
| 11/19/20 Devin/Kevin 2916/2316 Boomaxe Boomaxe |
| 11/19/20 Bill 2702/2703/2704 Patched, pick 2 yds oil 27, 22A |
| 2511/2507 up 10 tons in sand Malakoff |
| 11/19/20 Darrell/Kenny 2918 Overlay road 15 flowboys 120M, |
| Mike 375 tons of rosco |
| Wood roller |
| County D- |
| mix |
| 11/20/20 Bill/Kevin/ 2901/2112 Repaired base 28 yds crush Haul |
| Ray failures 2901, concrete, 2 truck, case |
| patch yds millings backhoe, |
| 23, 26 22, |
| 24 |
| 11/20/20 Kenny/Mike 2918 Overlay road 8 flowboys, 120M, |
| Devin 198 tons of rosco, 20B |
| Wood |
| County D- |
| mix |
| 11/23/20 Bill/Kevin 2621/2624/2115 Patch 3 yds oil 22 |
| 2312/2802/2816 sand |
| 11/23/20 Grady/Chase 2120/2702 Patch 3 yds oil 24 |
| sand |
| 11/23/20 Devin 2316/2309 Boomaxe, Boomaxe |
| changed filter |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used |
|----------|-----------------|---------------------|--------------------|--------------------|-------------------|
| | T | - 49 | 1 | T | T |
| 11/23/20 | Ray/Woody | 2434/2303/2313 | Patched | 1 yds | 22A |
| | | 2305/2302/2534 | | millings, 2 | |
| | | 2909 | | yds oil sand | |
| 11/23/20 | Kenny/Mike | 2918 | Overlay road | 14 | 120M, |
| | Darrell | | | flowboys, | rosco |
| | | | | 375 tons of | roller |
| | | | | Wood | |
| | | | | County | |
| | | | | asphalt D- | |
| 11/24/20 | Day/Waady | 2001 | Domainad | Mix | 22 |
| 11/24/20 | Ray/Woody | 2901 | Repaired shoulders | 4 yds | 22 |
| 11/24/20 | Grady/Chase | 2112/2602 | Patch | millings 3 yds oil | 24 |
| 11/24/20 | Grady/Chase | 2112/2002 | Fatch | sand | 24 |
| 11/24/20 | Devin | 2315/2309 | Boomaxe | Sand | Boomaxe |
| 11/24/20 | Bill/Kevin | 2121 | Installed two | 14 yds crush | Case |
| 11/24/20 | Mike/Kenny | 2121 | 15x24 | concrete | backhoe, |
| | Darrell | | culverst, | Concrete | haultruck |
| | Darren | | cleaned out | | 23, 23,27, |
| | | | ditches | | 28 |
| 11/30/20 | Mike/Ray | 2600's/2700's | Patch | 2 yds | 24 |
| 11,20,20 | 1villio, rtay | 2000 5/2/00 5 | mailboxes, | millings | |
| | | | pickup | | |
| | | | matters | | |
| 11/30/20 | Keivn/Bill | 2300's/2800's | Patched | 3 yds | 22 |
| | | 2900's | mailboxes | millings | |
| 11/30/20 | Kenny/Devin | 2309 | Boomaxe, | | Boomaxe, |
| | | | worked on | | 20R |
| | | | backhoe | | |
| 12/01/20 | Mike/Ray | 2600's/2100's | Put up county | | 22A |
| | | 2500's/2400's | road signs | | |
| 12/01/20 | Bill/Kevin | 2142/2119/2702 | Put up no thru | 2 yds oil | 22 |
| | | 2721/2704/2703 | signs, patched | sand | |
| 12/01/20 | Kenny/Devin | Shop | Worked on | | 20R, 20D, |
| | | | 20D, piled | | case |
| 1010115 | G 1 /== | | millings | | loader |
| 12/01/20 | Grady/Chase | 2141/2120 | Patched | 3 yds | 24 |
| 10/00/20 | Dill | 0410/0511/050= | D. I. I. | millings | 22.4 |
| 12/02/20 | Bill | 2410/2511/2507 | Patched and | 2 yds | 22A |
| | | /2510/2509 | pushup | millings | |
| 10/00/00 | Warring/D | 2000/2700/2200 | millings | 11 '11' | 22 |
| 12/02/20 | Kevin/Ray | 2800/2700/2300 | Patched mail | 1 yd milling | 22 |
| 12/02/20 | Chaga/M:1-a | 2405/2406/2512 | boxes | 2xxd milling = | 24 |
| 12/02/20 | Chase/Mike | 2405/2406/2513 | 2819/2820 | 2yd millings | 24 |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used | |
|----------|-----------------|---------------------|---------------|--------------|-------------------|--|
| - 50 - | | | | | | |
| 12/02/20 | Kenny/Devin | Worked in | | | | |
| | | shop, 20D, | | | | |
| | | boomaxe | | | | |
| 12/03/20 | Bill/Kevin | 2432/2511/2404 | Blade roads | 35 yds crush | 26, | |
| | Darrell | | | concrete, 1 | gradall, | |
| | | | | yd dmix | 22, 23, | |
| | | | | | 120M | |
| 12/03/20 | Devin/ | Boomaxe | 2309/2313 | | Boomaxe | |
| 12/03/20 | Chase | 2410/2414/2415 | Patch | 4 yds oil | 24 | |
| | | 2120/2404 | | sand | | |
| 12/03/20 | Kenny/Mike | 2628/2624 | Blade roads | 70 yds crush | 120H, 27, | |
| | Ray | | | concrete | 28 | |
| 12/04/20 | Chase/Stan | 2301/2120 | Patched, | 2 yds oil | 24 | |
| | | | picked up | sand | | |
| | | | brush | | | |
| 12/04/20 | Bill/Mike | 2624/2623/2622 | Blade roads | 84 yds crush | 120H, 26, | |
| | Kevin | | | concrete | 23 | |
| 12/04/20 | Kenny/Darrell | 2314 | Boomaxe, | | Boomaxe, | |
| | Devin | | | | 20, 20R, | |
| | | | | | backhoe | |
| 12/07/20 | Devin | Shop, worked | | | | |
| | | on Boomaxe, | | | | |
| | | burned brush on | | | | |
| | | yard | | | | |
| 12/07/20 | Chase | 2602/2120 | Patching | 5 yds old | 24 | |
| | | 2417 | | sand | | |
| 12/07/20 | Bill/Kevin | 2621 | Installed | 21 yds crush | Haul truck | |
| | Ray | | 24x36 | concrete | case | |
| | | | crossroad | | backhoe, | |
| | | | culvert | | 23, 26 | |
| 12/07/20 | Kenny/Mike | 2624/2622 | Blade Roads | 42 yds | 120H, 28 | |
| | | | | millings | · | |
| 12/08/20 | Bill/Kevin | 2304/2303/2305 | Patched, went | 2 yds oil | 26, 23, 22 | |
| | | 2306/2310/2602 | to Malakoff | sand | | |
| | | | for asphalt | | | |
| 12/08/20 | Devin | 2432 | Boomaxe | | Boomaxe, | |
| 12/08/20 | Chase/Ray | 2320/2301/2309 | Patched | 3 yds oil | 24 | |
| | | 2908/2621 | | sand | | |
| 12/08/20 | Kenny/Mike | 2622/2621/2119 | Blade roads | 56 yds crush | 120H, 26, | |
| | Darrell | | | concrete | 28 | |
| 12/09/20 | Bill/Kevin | 2112/2128/2144 | Patched | 2 yds oil | 22 | |
| | | 2507/2418/2416 | | sand | | |
| | | 2511/2534/2434 | | | | |
| 12/09/20 | Chase/Ray | 2112/2627/2629 | Patch | 2 yds oil s | 22A | |
| | , | | 1 | | | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | | Material | Equip Used | | |
|----------|-----------------|---------------------|---------------|------------------|-------------------|--|--|
| - 51 - | | | | | | | |
| 12/09/20 | Devin | Worked on | | | | | |
| | | 20R, and 24 | | | | | |
| 10/00/00 | - 11/77 | trucks | | 10 | 1207.5 | | |
| 12/09/20 | Darrell/Kenny | 2918 | Overlay road | 10 | 120M, | | |
| | Mike | | | flowboys, | rosco, 20B | | |
| | | | | 250 tons of Wood | | | |
| | | | | County D- | | | |
| | | | | mix | | | |
| 12/10/20 | Devin | Worked on | | IIIIX | | | |
| 12/10/20 | Devin | 22A, and 20, | | | | | |
| | | maintenance | | | | | |
| 12/10/20 | Bill/Mike | 2417/2918/2916 | Cleaned out | 35 yds | 120M, | | |
| | Kevin/Kenny | 2903/2309/2313 | ditches, | millings, 1 | haultruck | | |
| | Darrell | | repaired road | yd oil sand | 26, 23, 28, | | |
| | | | 2417, patched | | SDLG | | |
| 12/10/20 | Chase/Ray | 2120/2112/ | Patch | 3 yds oil | 24 | | |
| | | cherry creek | | sand | | | |
| | | 2414 | | | | | |
| 12/11/20 | Bill/Kevin | 2913/2910/2912 | Patched mail | 2 yds | 22 | | |
| | | /2917/ 2102 | boxes | millings | | | |
| 21/11/20 | Ray | 2414 | Patched | 1 yd | 24 | | |
| 10/11/00 | D : /II | XX7 1 1 | | millings | | | |
| 12/11/20 | Devin/Kenny | Worked on | | | | | |
| | | 20D, Big army truck | | | | | |
| 12/14/20 | Kevin/Bill | 2627/2621/ | Patch | 2 yds of oil | 22 | | |
| 12/14/20 | KCVIII/DIII | 2100's | 1 atch | sand | 22 | | |
| 12/14/20 | Chase/Ray | 2514 | Patch | 3 yds | 24 | | |
| 12/11/20 | Shape, Italy | 2311 | | millings | | | |
| 12/14/20 | Devin | 2913 | Boomaxe | 8- | Boomaxe | | |
| 12/14/20 | Kerry/Mike | 2621 | Blade road, | 7 yds crush | 120H, | | |
| | , | | packed trash | concrete | backhoe | | |
| 12/15/20 | Devin | 2913 | Boomaxe | | Boomaxe | | |
| 12/15/20 | Chase | 2514/2513/2112 | Patch | 3.5 yds oil | 24 | | |
| | | 2120 | | sand | | | |
| 12/15/20 | Bill/Kevin | 2141/2115/lake | Patch | 2 yds oil | 22 | | |
| | | wood2908/2909 | | sand | | | |
| 10/15/20 | TZ /3 5'1 | 2912/2910 | DI I ' | <i>56</i> 1 | 10011 00 | | |
| 12/15/20 | Kenny/Mike | 2129/2621/2703 | Blade roads | 56 yds | 120H, 28, | | |
| | Ray | | | concrete, 9 | 26, 22A | | |
| 12/16/20 | Devin | Worked on | | yds oil sand | | | |
| 12/10/20 | Devill | 1985 chev truck | | | | | |
| | | 1705 CHEV HUCK | | | | | |

^{*}Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material *Oil Sand material is AC 20 Asphalt

| Date | Employee | County Roads | Work Done | Material | Equip Used | | | | |
|----------|-----------------|---------------------|------------------|--------------|-------------------|--|--|--|--|
| - 52 - | | | | | | | | | |
| 12/16/20 | Chase/Ray | 2514/2703/2405 | Patch | 3 yds oil | 24 | | | | |
| | | | | sand | | | | | |
| 12/16/20 | Bill/Kevin | 2300's | Patch | 1 yd oil | 22 | | | | |
| | | | | sand 1 yd | | | | | |
| | | | | millings | | | | | |
| 12/16/20 | Kenny/Mike | 2128 | Blade road | 28 yds crush | 120H, 28 | | | | |
| | | | | concrete | | | | | |
| | | | | | | | | | |