

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 1 -

01/04/21	Devin	2710/2711	Boomaxe		Boomaxe
01/05/21	Ray/Chase	2908/2519/2147 Cherry Ck, 2101/2120	Patched	2 yds oil sand	24
01/05/21	Bill/Kevin	2721/2719/2705	Pick up 2 loads oil sand, patched	3 yds oil sand	23, 26, 22
01/05/21	Devin	2711/2712	Boomaxe		Boomaxe
01/05/21	Kenny/Mike Darrell	2807/2806	Patched, hauling material.	3 yds oil sand	Backhoe, 22A, haultruck
01/06/21	Bill/Kevin Devin	2716/2721/2702 2703/2704	Patched, worked on 22	3 yds oil sand	22
01/06/21	Ray	2720	Patched	4 yds oil sand	24
01/07/21	Kenny/Darrell	Worked on 28, put new tires on truck			
01/07/21	Ray	2719/2721/2705 2804/2712/	Patched, pickup oil tires	1 yds oil sand, 2 yds millings	22A
01/07/21	Bill/Kevin	2308/2704	Cross Culvert	91 yds O/S	23, 24BH
01/08/21	Kenny/Mike Ray/Devin	2506	Blade road, worked on 22A, 28	42 yds crush concrete	120M, 27, 26
01/08/21	Ray/Chase	2128, 2602	Patched	2 yds oil sand	24
01/11/21	Ray	2145/2129	Patched, worked on 22A	1 yd millings	22A
01/11/21	Bill/Kevin	2100's	Patched mail box shoulders	2 yds millings	22
01/11/21	Devin	Shop, worked on 28, 22, SDLG			
01/11/21	Kenny/Mike	Patched	Patched mail box shoulders	2 yds millings	24
01/12/21	Chase/Mike	2306/2307/2702	Patch	3 yds oil sand	24
01/12/21	Ray	2129/2602/2120	Patched mail boxes	3 yds millings	22A
01/12/21	Bill/Kevin	2519/2521/2205 2210/2209/2207 2202/2206/	Patched mail boxes	3 yds millings	22

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 2 -

01/12/21	Devin	Worked on dump truck 23			
01/13/21	Bill/Kevin	Cherry Ck, 2120/2101/2115 2116/2143	Patched	3 yds oil sand	22
01/13/21	Chase/Mike	2303/2307/2304 2301	Patch	3 yds oil sand	24
01/13/21	Devin/Woody	2409/2412/2424 2402/2420/2403 2431	Patch	3 yds oil sand	22A
01/13/21	Kenny	Piled rock in yard			
01/14/21	Chase/Woody	2702/2703/2406 2507	Patch	4 yds oil sand	24
01/14/21	Bill/Kevin	2918/2310/2721	Picked up two loads of mix Malakof, patch cave ins	4 yds oil sand	26, 23, 22
01/14/21	Kenny/Mike	2628	Blade roads	35 yds crush concrete	120M, 28
01/14/21	Ray/Devin	2702/2703/2801 2804/2806	Patched	4 yds oil sand	22A
01/15/21	Chase/Woody	2126/2147/ Myrtle Springs	Patching	3 yds oil sand	224
01/15/21	Ray/Devin	2404/2418/2511 2606/2421	Patch	3 yds oil sand	22A
01/15/21	Bill/Kevin	2205/2200/2205 2202/2207/2208 2209	Patched	3 yds oil sand	22
01/15/21	Kenny/Mike	3440/3445	Piled rock, blade road	42 yds crush concrete	120H, 28
01/19/21	Ray/Mike	2300's, 2900's	Patched, cut tree off 2316	3 yds oil sand	24, chainsaws
01/19/21	Bill/Kevin	2100's	Patched roads, pushed rock	2 yds oil sand	22
01/19/21	Kenny/Devin Darrell	2314/2322/2316 2305/2801/2316	Replaced roads signs that were stolen	8 signs, brackets and post	21R
01/20/21	Chase/Woody	2304/2801/2816	Pickup brush 2304, patched	3 loads brush, 2 yds oil sand	24

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 3 -

01/20/21	Kenny/Mike	2137/2316	Cut up tree on road 2316, blade 2137	21 yds rock/milling	120H, 28
01/20/21	Bill/Kevin Devin/Ray	2316/2137/2410 2415	Clean up tree on 2316, haul rock/millings	28 yd millilngs, 1 yd oil sand	Backhoe, 25, 20R, 22A
01/20/21	Devin/Ray	2408/2433/2602 2406/2601/2316	Help clean up massive tree on 2316, patched	1 yd oil sand	22, 2/4 ton pickup, chainsaw, backhoe, 25
01/21/21	Chase/Woody	2501/2316/ Myrtle Springs 2147	Patch	4 yds oil sand	24
01/21/21	Devin	Worked on 23			
01/21/21	Billy/Ray	2702/2801/2816 2808/2924/2923	Clean out ditch on 2702, patched	2 yds oil sand	Case backhoe, 26, 22
01/21/21	Kenny/Mike	2129/2146	Blade roads	35 yds crush concrete	120H, 28
01/22/21	Devin	2702	Boomaxe		Boomaxe
01/22/21	Ray	2534/2511	Patched	5 yds oil sand	22A
01/22/21	Chase/Woody	2602/2518/2517 2506/2120	Patch	3 yds oil sand	24
01/22/21	Bill/Kevin	2421/2404/2142 2414/2415/2410	Patch	2 yds oil sand	22
01/22/21	Kenny/Mike	2128	Blade road	14 yds crush concrete	120H, 28, backoe
01/25/21	Ray/Woody	2511/2142/2410 2512/2128/2112	Patch	4 yds oil sand	22A
01/25/21	Chase/Devin	2716/2721/2301 2302	Patched, cut tree up 2302	3 yds oil sand	24
01/25/21	Bill/Kevin Mike	2902/2915/2914 2916	Patched 2902 with millings, patched	3 yds millings, 2 yds oil sand	22
01/26/21	Devin	2703	Boomaxe		Boomaxe
01/26/21	Bill/Kevin	2918/2800's	Patch	3 yds oil sand	22
01/26/21	Ray	2912/2910/2901 2312/2629/2627	Patch	3 yds oil sand	22A

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 4 -

01/26/21	Kenny/Mike	2314/2916/2813 2313	Put up road signs, cut tree 2313	3 signs 1 post, 2 brackets	21R, 25, backhoe
01/26/21	Chase/Woody	Cherry ck, 2120 2716/2708/2701 2421	Patch	4 yds oil sand	24
01/27/21	Devin	2637/2421	Boomaxe		Boomaxe
01/27/21	Bill/Kevin Darrell	2432/2425/2410 2418/2414/2432 2426	Blade 2432, 2425, patched	63 yds concrete, 2 yds oil sand	120M, 26, 23, 23, 22
01/27/21	Chase/woody	2703/2701/2147 2909/2912/2901	Patch	4 yds oil sand	24
01/27/21	Kenny/Mike Ray	2406	Blade	119 yds crush concrete	120H, 28, 27
01/28/21	Bill/Kevin Darrell	2303/2304/2306 2316/2318/2319	Blade 2303, patched	63 yds crush concrete, 2 yds oil sand	120M, 23, 26, 22
01/28/21	Chase/Woody	2901/2120/2141	Patch	4 yds oil sand	24
01/28/21	Devin	Worked on Boomaxe			
01/28/21	Kenny/Mike Ray	2406	Blade road	105 yds crush concrete, millngs	120H, 28, 27
01/29/21	Devin/Ray	2903/2621/2627 2629	Patched	1 yds oil sand	24
01/29/21	Bill/Kevin Darrell	2902/2903/2914 2910/2916	Patched, blade 2902	77 yds millings, 2 yds oil sand	120M, 23, 26, 22
01/29/21	Kenny/Mike	2403/2409	Blade roads	47 yds crush concrete	120H, 28
02/01/21	Bill/Kevin Ray	2205/2301/2319	Cleaned out culvert 2205, patch	1 yd oil sand	Haul truck, 23, 26, 22
02/01/21	Ray	2804/2802/2120 2602/2624/2630	Patched	1 yd oil sand	22A, 26
02/01/21	Chase/Woody	2901	Patch	4 yds oil sand	24
02/01/21	Devin	Worked on boomaxe			

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 5 -

02/01/21	Kenny/Mike	2405	Blade road	42 yds concrete/millings	28, 120H
02/02/21	Devin	Worked on 28, 27, and pushed concrete			
02/02/21	Bill/Kevin	2801/2309/2721 2702/2704/2703 2514	Cleaned out culvert 2801and straighten mail box, patched	2 yds oil sand, 21 yds concrete 2414	22/26
02/02/21	Ray/Woody	2601/2436/2431 2433/2805/2817	Patched, picked up trash 2601	3 yds oil sand	24, 22
02/02/21	Kenny/Mike Bill	2431/2514	Blade roads	77 yds crush concrete.	120H, 28, 27
02/03/21	Kenny/Mike	2514/2513	Blade roads	56 yds crush concrete	120H, 28
02/03/21	Devin	Worked on 24, pushed up concrete, hauled 7 yds oilsand	2301/2309 intersection	7 yds oil sand	27
02/03/21	Bill/Kevin	2432/2534/2812 2803/2806/2807	Put signs up 2432, child play 2534, patch	2 yds oil sand	22
02/03/21	Ray	2500'/2400's	Patch	3 yds oil san	24
02/03/21	Chase/Woody	2909/2302/2311	Patch	4 yds oil sand	22A
02/04/21	Devin	Worked on 20A, 2303	boomaxe		Boomaxe
02/04/21	Ray	2505/2506/2507 2508	Patched	2 ½ yds oil sand	26, 22A
02/04/21	Bill/Kevin	2511/2119/2120 2101/2102/	Patched	3 yds oil sand	22
02/04/21	Chase/Woody	Cherry Blossom 2602/2309/2120	Patch	4 yds oil sand	24
02/04/21	Kenny/Mike Ray	2315	Blade road	56 yds crush concrete	120H, 28
02/05/21	Devin	2303	Boomaxe		Boomaxe
02/05/21	Woody	2913/2901/2725 2715/2722/2708 Lakewood/2105	Patched, pick up trash 2901	3 yds oil sand	22A

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date	Employee	County Roads	Work Done	Material	Equip Used
-------------	-----------------	---------------------	------------------	-----------------	-------------------

- 6 -

02/05/21	Bill/Kevin	2506/2315/2501 2310/2318/2409	Put children at play 2506, street sign 2315, patch	3 yds oil sand	22
02/05/21	Kenny/Mike	2620	Blade road	42 yds concrete/millings	120H, 28
02/08/21	Devin/Mike	Cherry cheek/ Lakewood trails	Repaired tire, on Terex, pack trash, patched	2 yds oil sand	24
02/08/21	Ray/Woody	2120/2105/2112 2410/	Patched, cut tree up on 2410, pickup tires off road	2 yds oil sand	22
02/08/21	Kenny/Bill Kevin	2703	Repaired base failures	49 yds crush concrete	Backhoe, 23, 28
02/09/21	Devin/Mike	2100's	Patched	2 yds oil sand	24
02/09/21	Ray/ Woody	2507/2516/2319 2309/	Patched	2 yds oil sand	22
02/09/21	Kenny/Bill Kevin	2703	Repaired base failures	49 yds crush concrete	Case backhoe, 23, 28
02/10/21	Mike/Devin	2716/2708/2700 's, took 27 and 22 to be inspected	Pick up 11 bags trash 2716, patch tire on Trex	2 yds oil sand	27, 22 24
02/10/21	Kenny/Bill Kevin	2703/2702	Repaired base failures	49 yds crush concrete	Case backhoe, 23, 28
02/10/21	Ray	2900's/ 2602 2623	Patched	2 yds oil sand	22
02/11/21	Bill/Mike Ray/Darell	Worked on all equipment getting freeze proof.			
02/12/21	Bill/Kevin	2100's/2500's	Patched shoulders, Mailboxes	2 yds millings	24
02/12/21	Devin	Worked on fuel tank/ shop			
02/12/21	Mike	Worked in yard			

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 7 -

02/12/21	Ray	2504/2512/2112 2128/2124	Patched	2 yds oil sand	22
02/16/21	Bill/Ray Mike/Darrell	Txdot roads Snow storm	Blade		120H, 120M, 22
02/17/21	Bill/Ray Mike/Darrell	Txdot roads snow storm	Blade		120H, 120M, 22
02/18/21	Mike/Darrell	Txdot roads Snow storm	Blade		120H, 120M
02/22/21	Bill/Kevin	2700's	Patched	3 yds oil sand	22
02/22/21	Ray/Woody	2139/2128/2120 2534/2124/2517 2518	Patched and picked up trash	2 yds oil sand	24
02/22/21	Devin/Mike Kenny/Darrell	Worked in shop, 120H, 120M, tires			
02/23/21	Bill/Kevin	2318/2801/2802 2804/2806	Installed 15x30 culvert, 2318	7 yds crush concrete, 2 yds oil sand	Haultruck case back hoe, 23 22
02/23/21	Ray/Woody	2410/2404/2112	Patched repaired signs on 2404	1 ½ yds oil sand, poles and signs	22
02/23/21	Devin/Mike	Worked on 22, pipes that had busted			
02/23/21	Kenny	2603	Packed trash, put up dead end sign 2603		
02/23/21	Bill/Kevin	2816/2819/2815	2813/2810	4 yds oil sa	22A
02/24/21	Devin/Mike	2602/2604	Patch, got water from Pct.1	2 yds oil sand	22A
02/24/21	Ray/Woody	2112/2140/2306 2303	Patch	1 yd oil sand, 3 yds millings	24
02/25/21	Ray/Woody	2145/2500's 2400's/2120	Patch	1 ½ yds	22
02/25/21	Bill/Kevin	2923/2908/2924 2901/2317/2318 2310/2309	Patch	3 yds oil sand	22
02/25/21	Devin	2311/2310	Boomaxe		Boomaxe
02/25/21	Kenny/Mike	2600's	Patch	2 yds oil sand	22A

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 8 -

02/26/21	Kenny/Mike Devin	Maintenance on all patch trucks			
02/26/21	Bill/Kevin	2404/2403/2309 /2219/2216	Fixed sign on 2404, patched, repaired tire 22	1 yd oil sand	22
03/01/21	Devin	Worked in shop			
03/01/21	Bill/Kevin	2500's	Patched	2 yds oil sand	22
03/01/21	Kenny/Mike	2708/2421/2124	Blade roads, patched	1 yd oil sands, 2421, 2124, 14 yds rock	120H, 28, 22A
03/01/21	Ray/Woody	Myrtle springs, 2100, 2512,	Patched	2 yds oil sand	24
03/02/21	Ray/Woody	Cherry creek, 2100,	Patched	2 ½	24
03/02/21	Bill/Kevin	2120/2134/2142 2117/2115	Patched	3 yds yds oil sand	22
03/02/21	Devin	2317/2318	Boomaxe		Boomaxe
03/02/21	Kenny/Mike	2602	Put up road sign, patched	1 sign, 2yds oil sand	22A
03/03/21	Devin	2719/2721/2718 2813	Patched, strip patched	Patched 2 yds oil sand, 14 yds oil sand 2813	22, 28
03/03/21	Ray	2622	Blade road, patched	2 yds oil sand, 14 yds rock crush concrete	26, 22
03/03/21	Woody	2808/2809/2812 2813	Patch	2 yds oil sand	24
03/03/21	Mike/Kenny Kevin/Ray	2623/2622	Blade roads, repaired base failures	35 yd crush concrete, 7 yds oil sand	120H
03/04/21	Devin	2705/2310	Patched	1 yd oil sand	224
03/04/21	Ray/Woody	2304/2302/2301 2303/2204/2210	Patched	3 yds oil sand	22
03/04/21	Bill/Kevin	2704/2703/2702 2431/2430/2120 2101/cherry ck	Patched	3 yds oil sand	22A
03/04/21	Kenny/Mike	2624/2623/2622	Blade Roads	42 yds crush concrete	120H, 28

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 9 -

03/05/21	Bill	2717/2430/2413 2415/2721/2201	Pickup load of D-mix, patched	3 yds oil sand	26, 22D
03/05/21	Kevin/Ray	2300's	Patch	2 yds oil sand	22
03/05/21	Kenny/Mike	2128/2129	Blade roads	4 yds crush concrete	120H, 28
03/08/21	Ray/Woody	2144/2506/2507 2138	Patched	2 ½ yds oil sand	24
03/08/21	Darrell/Kevin	2432/2428	Blade roads	42 yds crush concrete	23, 120M
03/08/21	Kenny/Mike Bill	3440/3441/2628 2602	Blade roads	70 yds crush concrete	120H, 28, 26
03/08/21	Devin/Kevin	2705/2708	Patch	2 yds oil sand	22A, 20R, ¾ ton
03/09/21	Darrell/Kevin	2506	Blade road	28 yds crush concrete	120M, 23
03/09/21	Ray/Woody	2624/2625/2627 2434/2402/2923	patch	2 ½ yds oil sand	24
03/09/21	Devin/Kevin	2416/2414/2501 2502	Patch	2 yds oil sand	22
03/09/21	Kenny/Mike Bill	2147/2514/2620	Blade roads	70 yds crush concrete	120H, 26, 28
03/10/21	Devin	Piled rock at barn			SDGL
03/10/21	Bill/Kevin	2403	Repaired base Failures	49 yds crush concrete	Case backhoe, 23, 27
03/10/21	Woody	2410/2427/2501 2505/2122/	Cherry/patch blossom	Patch	24
03/10/21	Mike/Darrell	2506	Strip patched	21 yds oil sand	25, 120M
03/11/21	Ray	2520	Patched, cave ins	1 yd oil sand	24
03/11/21	Bill/Mike Ray	2120/2115/2109 2206	Installed 15x24 culvert 2120, patched, patched	14 yds crush concrete, 1 yd oil sand	Case backhoe, 28, 27, 24
03/11/21	Devin	Worked on boomaxe, pushed up rock			SDGL
03/12/21	Bill/Kevin	2722/2705/2704 2703/2418	Patched	4 yds oil sand	22A

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 10 -

03/12/21	Kenny/Mike	2602	Blade road	35 yds crush concrete	120H, 28
03/12/21	Ray	2816/2802/2803 2815/2813/2702 2816	patched	2 yds oil sand	24
03/12/21	Devin	Worked on pushing rock up in yard			
03/15/21	Devin	Worked in shop and pushed milling up			
03/15/21	Ray/Woody	2306/2307/2301	Patch	5 yds oil sand	24
03/15/21	Kevin/Bill	2702/2701/2705	Patch	2 yds oil sand	22
03/15/21	Kenny/Mike	2140/2146	Blade roads	21 yds crush concrete	120H, 28, Backhoe
03/16/21	Ray/Rodney	2304/2301/2307 2901/2916/2918 2903	Patched	3 yds oil sand	224
03/16/21	Devin	Worked in shop, repaired old Boomaxe, pushed up rock			SDLG
03/16/21	Bill/Kevin	2316/2319/2318 2317/2511/2516 2517/	Patched	2 yds oil sand	22
03/16/21	Kenny/Mike	2406/2405	Blade roads	21 yds crush concrete/ millings	120H, 28
03/17/21	Ray/Woody	2620, 3443 picked up tires, 2205, 2138, 2115, 2118	Patched, picked up tires	1 yd oil sand	224
03/17/21	Bill/Kevin	2434/2114/2410 2504/2404/2112 2414/2412	Fixed no thru truck sign 2434, patched	2 yds oil sand	22
03/17/21	Kenny/Mike Devin	Worked on 120H, case loader, piled millings			
03/18/21	Ray/Woody	2112/2519/2512 2521/2602/2604 2621	patched	2 yds oil sand	24

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 11 -

03/18/21	Devin/Mike Kenny	Worked on 120H, 28			
03/18/21	Bill/Kevin/ Mike Kenny Devin	2506	Cut tree down and hauled off, patched	1 yd oil sand	Haul truck, case backhoe, 25, 22A, 22, 20R
03/19/21	Devin/Mike Kenny	Worked on rosco roller, cleaned shop			
03/19/21	Bill/Kevin	2120/2112/2139 2144/2136/2138	Patched	2 yds oil sand	23
03/19/21	Ray	2418/2404/2200 2201/	Patched	1 yd oil sand	24
03/22/21	Bill/Kevin	2120/2146/2124 2116/2512/2411	Patched	2 yds oil sand	22
03/22/21	Devin/Mike	2901/2908/2912 2910/2903/2916 2918/2924	Patch	3 yds oil sand	22A
03/22/21	Ray/Woody	2205/2307/2504 2508/2502/2801 2725/2715	Patched	2 yds oil sand	24
03/23/21	Chase/Woody	2802/2807/2808 2803	Patched	2 yds oil sand	24
03/23/21	Mike/Kenny	2303/2305	Strip patched roads	21 yds oil sand, 42 yd crush concrete	28, 120H
03/23/21	Devin/Darrell	2423	Blade roads	49 yds crush concrete	120M, 26
03/23/21	Bill/Kevin Ray	2924/2311/2307 2303/2212	Cleared cross road pipe 2924, Repaired base failures	24 yds crush concrete, 1 yd oil sand	Case backhoe, 23 ,27, 25, 22A
03/24/21	Bill/Kevin	2808/2816/2144 2128/2129/2146 2802	Cleaned out crossroad culverts, patched	1 yd oil sand	Haultruck, Backhoe, 25, 22A
03/24/21	Ray/Woody	3204/3447/3448	Patched	3 yds oil sand	24
03/24/21	Kenny/Devin	2146	Boomaxe		Boomaxe 21R

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 12 -

03/25/21	Devin/Ray	2600's	Check for down trees, patched	1 yd oil sand	24
03/25/21	Bill/Kevin	2721/2702	Check for down trees, patched	2 yds oil sand	22A
03/25/21	Kenny/Mike	2318/2918	Patched, picked up tree limbs	1 yd oil sand	22
03/26/21	Kenny/Mike	2534/2511	Patched	2 yds oil sand	22A
03/26/21	Bill/Kevin	2501/2517/2516 2518/2511	Patched	3 yds oil sand	22
03/26/21	Ray/Devin	2144/2146	Patched, boomaxe	1 yd oil sand	24
03/29/21	Woody	2301/2304	Patched	2 yds oil sand	24
03/29/21	Devin/Darrell	2146	Burn brush, welded boomaxe boom		
03/29/21	Kenny/Bill Kevin/Mike	2120	Repaired base failures	77 yds crush concrete	23 27, 28, Backhoe
03/30/21	Woody	2602/2145	Patch	2 yds oil sand	22
03/30/21	Devin	2126	Boomaxe		Boomaxe
03/30/21	Mike/Kevin Bill/Ray	2120	Repaired base failures	77 yds of crush concrete	120H, Case Backhoe, 27, 23
03/30/21	Kenny/Darrell	2814/2120	Blade roads	49 yds C C	28,120M
03/31/21	Woody	2145/2502	Patch	2 yds oil sand	22
03/31/21	Devin	2128	Boomaxe		Boomaxe
03/31/21	Kenny/Mike Ray/Bill/ Kevin	2120/2602	Repaired base failures	56 yds crush concrete	Backhoe, 23 26, 28, 120H
04/01/21	Ray/Woody	2144/2627/2701 2301	Patch	2 yds oil sand	24
04/01/21	Devin	2128	Boomaxe		Boomaxe
04/01/21	Kenny/Mike	2301/2403	Repaired base failures	14 yds crush concrete	120H, 28
04/01/21	Bill/Kevin	2602/2301/2309 2219/2317	Fix CR pipe, 2602, patch	9 yds oil sand	CBackhoe 23, 22

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 13 -

04/05/21	Woody/Chase	2120/cherry ck/ Cherry Blossom	Patch	3 yds oil sand	24
04/05/21	Devin	2128	Boomaxe		Boomaxe
04/05/21	Ray	2708/2811/2709 2705/2708	Patched	1 yd oil sand	22A
04/05/21	Bill/Kevin Ray	2405/2517/2518 2301/2309	Clean up trees, 2403,2517, cleared ditch 2517, cleaned beaver nest 2518, patched	2 yds oil sand	Case backhoe, 25, 22A, 22
04/05/21	Kenny/Mike Darrell	2301	Strip patched, piled rock	28 yds oil sand	120M, 28, backhoe, SDL loader
04/06/21	Ray/Woody	2709/2120/2144 2112/2124	Patched	2 yds oil sand	24
04/06/21	Devin	2128/2129	Boomaxe		Boomaxe
04/06/21	Kenny/Mike Kevin	2924/2908	Strip patched	35 yds oil sand	120H, 28, 23, SDLG
04/06/21	Bill/Kevin Darrell	2501/2705	Put up speed limit 2501, blade road	28 yds crush concrete	120M, 23, 26, 22
04/07/21	Kenny/Mike	2924/2120	Strip patched roads	28 yds oil sand	120H, 28
04/07/21	Devin	2129/2149	Boomaxe		boomaxe
04/07/21	Woody/Chase	2721/2706/2621	Patch	3 yds	
04/07/21	Bill/Kevin Darrell	2120/Lake view dr.	Installed 15x24, 2120, big rock end of culvert lakeview	14 yd crush concrete, 7 yds big rock	Case backhoe, 23, 27
04/07/21	Ray	2501/2112	Patched	2 ½ yds OS	22
04/08/21	Kenny/Mike Darrell	2318	Strip patched road	28 yds of oil sand	120M, 26, 28
04/08/21	Ray/Chase	2721/2804/2507	Patch	4 yds oil sand	24
04/08/21	Devin	Worked on 120H			
04/08/21	Bill/Kevin	2801/2802/2807	Patched	3 yds oil sand	22
04/09/21	Devin	2149	Boomaxe		Boomaxe

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 14 -

04/09/21	Bill/Kevin	2318/2316/2309 2301/2311/2317 2316	Patched	3 yds oil sand	22
04/09/21	Ray/Chase	2721/2816/	Patched	2 ½ yds oil sand	24
04/09/21	Kenny/Mike	2309/2313/2602	Patched	2 yds oil sand	22A
04/12/21	Bill/Keivn Ray	2901	Repaired base failures	50 yds crush concrete	Case backhoe, 23, 27
04/12/21	Chase/Woody	2401/2435/2411 2511/2516	Patch	5 yds oil sand	24
04/12/21	Devin	Worked on backhoe			
04/12/21	Kenny/Mike	2124	Put up yield sign, picked up culvert, packed trash	Post and sign	22A, backhoe.
04/13/21	Devin/Ray	2207/shop	Repaired culvert and ditch 2207, changed cutting blades on 621B		621B, 20R
04/13/21	Bill/Kevin Ray/Devin	2207/2209/2208 2205/2210/2206 2202	Installed 4' extension on culvert, 2207 patched	7 yds crush concrete, 1 yd oil sand	Haul truck, case backhoe, 23, 22, 20R
04/13/21	Mike/Kenny	2146/2129/2128	Blade roads	28 yds crush concrete	120H, 28, SDLG
04/13/21	Chase/Woody	2120/cherry ck, 2101/2501	Patched	4 yds oil sand	24
04/14/21	Ray/Woody	2501/2507	Patch	3 yds oil sand	24
04/14/21	Devin	2208/2209	Boomaxe		Boomaxe
04/14/21	Bill/Kevin Mike	2625/2630/2631 2621	Blade 2625 patched rest	21 yds crush concrete, 1 yds oil sand	Haul truck caseback hoe, 120H, 23, 26, 27
04/14/21	Kenny/Mike Darrell	2623/3440	Blade road 2623, picked up trash on 3440	7 yds crush rock	120H, 28, 20
04/15/21	Bill/Kevin	2607/2621	Patched	3 ydsoilsand	22

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 15 -

04/15/21	Chase/Woody	2114/2119/2501	Patched	3 yds oil sand	24
04/15/21	Darrell/Mike	2411/2119/2209	2411, cut tree limbs, repaired culvert 2119, boomaxe	1 yd oil sand	boomaxe
04/15/21	Ray	3225	Patched	4 yds oil sand	22A
04/16/21	Bill/Kevin	3440/3443/3449 3448/3449/2102	Patched, cut tree on 2102	3 yds oil sand	22
04/16/21	Devin/Mike	3449/3447/3440 2101/ worked on 22A	Patched, cut tree on 2102	2 yds oil sand	22A,
04/19/21	Devin	2209	Boomaxe		Boomaxe
04/19/21	Kenny/Mike Darrell	2141/2211	Strip patch 2141, blade 2211	14 yds oil sand 28 yds crush concrete	120M, 28, 27, 20R
04/19/21	Keivn/Ray	2115/2141/2117	Patched	2 yds oil sand	23, 27, 22
04/19/21	Chase/Woody	2306/2304	Patched	4 yds oil sand	24
04/20/21	Ray	Myrtle Springs	Patched	4 yds oil sand	22A
04/20/21	Devin	2901	Boomaxe		Boomaxe
04/20/21	Chase/Woody	2304/2403/2602	Patch	4 yds oil sand	
04/20/21	Bill/Kevin Mike	2916/2918/2901 2309	Patch cave in 2916,	2 yds oil sand	25, 23, 28
04/20/21	Kenny/Mike	2517	Put up slow child signs	Signs/posts	20R backhoe, case loader
04/21/21	Chase/Woody	2403/2602/2404	Patch	4 yds oil sand	24
04/21/21	Ray	Myrtle Springs, 2117/2143	Patched	3 yds oil sand	22A
04/21/21	Bill/Kevin	2807/2806/2810 2808/2816/2815	Patched	3 yds oil sand	22
04/21/21	Kenny/Mike	2627/2628	Blade roads, mowed yard	14 yds crush concrete, 4 yds oil sand	120H, 26, lawn mower
04/21/21	Devin	2901	Boomaxe		Boomaxe

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used
- 16 -

04/22/21	Devin	2901	Boomaxe		Boomaxe
04/22/21	Bill/Kevin Darrell	2421/2414/2814 2814/2816/2802 2801/2813	Cave-in 2421, strip patched 2414, patched	14 yds of new mix(spt), 14 yds millings, 3 yds oil sand	120H, 24, 23, 22
04/22/21	Kenny/Mike	2129/3440/2137	Blade roads	28 yds crush concrete	120H, 28
04/22/21	Chase/Ray	Cherry ck, 2101 2518/2128/	Patched	4 yds oil sand	24
04/23/21	Mike/Darrell	2602	Worked on SDLG, 120H, haultruck checked culvert on 2602		20R
04/23/21	Bill/Kevin	2415/2410/2414 2404/2416/2426	Patched	3 yds oil sand	22
04/23/21	Ray/Devin	2415/2901/2112	Patched	2 yds oil sand	24
04/26/21	Kevin	2702	Boomaxe		Old boomaxe
04/26/21	Chase/Woody	2301/2721/2708	Patch	4 yds oil sand	24
04/26/21	Devin	2901	Boomaxe		Boomaxe
04/26/21	Kenny/Darrell	2318/2918/2901 Ozark Road	Cut tree 2318, burned pile, patched	1 yd oil sand	20 chain, 22A
04/26/21	Bill/Ray	2506/2507/2504 2509/2510	Patched	3 yds oil sand	22
04/27/21	Bill/Ray	2511/2516/2517 2518/2507/2318	Patched	3 yds oil sand	22
04/27/21	Chase/Woody	2721	Patch	7 yds oil sand	24
04/27/21	Devin	2319	Boomaxe		Boomaxe
04/27/21	Kenny/Darrell	2411/2413/2702	Patched	Boomaxe on 2702	Boomaxe, 22A
04/28/21	Devin	2319	Boomaxe		boomaxe
04/28/21	Bill/Kevin Ray/Kenny Darell	2813	Strip patched road	98 yds oil sand	120M, 26, 23, 27, 28
04/28/21	Woody	2721/2703	Patched and washed 22	3 yds oil sand	22

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 17 -

04/29/21	Ray/Devin	2705	Patched	5 yds oil sand	22A
04/29/21	Chase/Woody	2705	Patched	2 yds oil sand	24
04/29/21	Kenny/ Darrell/Mike	Worked in shop			
04/29/21	Bill/Kevin	2702/2704/2708	Patched	43 yds oil sand	22
04/30/21	Devin/Kenny	Worked on trailer			
04/30/21	Bill/Kevin	2101/2102/2120 Cherry Ck, 2122/2505/2501	Patched	3 yds oil sand	22
04/30/21	Ray	2703/2705/2708	Patched	3 yds oil sand	24
05/03/21	Kevin	2703	Boomaxe		Boomaxe
05/03/21	Chase/Woody	Cherry ck, 2120/ 2602/2504	Patched	4 yds oil sand	24
05/03/21	Bill/Kenny Ray	2506/2702/2719 2144/2410	Clean up tree 2506, patch, pick up mix Malakoff	3 yds oil sand	22, 25, 26,
05/03/21	Devin	2319/2318	Boomaxe		Boomaxe, new.
05/03/21	Kenny/Darrell	2506	Hauled off tree, packed trash		Backhoe, 25
05/04/21	Chase/Woody	2112/2318	Patching	3 yds oil sand	24
05/04/21	Ray	2418/2311	Patching	2 yds oil sand	22A
05/04/21	Bill/Kevin Mike/Ray	2506/2512/2516 2518	Hauled mix from Malakoff, clean up trees, 2516/2518		Haul truck case back hoe, 23, 25, 28
05/04/21	Kenny/Devin	2506/2512/2516 2518	Cut and hauled off trees		20R, 25, 28, chain saws
05/05/21	Chase/Woody	2918/2306/2301 2414	Patch	4 yds oil sand	24
05/05/21	Bill/Kevin	2434/2306/2303 2307	Repaired base failure 2434	2yd oilsand 3yds concret	Ht, BH, 23, 22

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used
- 18 -

05/05/21	Kenny/Mike Darrell	2301	Overlay road	15 flowboys 373 tons of Wood Co. D-Mix	120M, Rosco roller
05/05/21	Ray/Devin	2112/2702/2144 2142	Patched 2702, cleaned up trees on roads	2 yds oil sand	22
05/06/21	Bill/Kevin	2307/2704/2311 2313/2304	Repaired cross road pipe 2307, patched, cut tree out of bridge 2704	2 yds oil sand	Case backhoe, 23, 20R, 22
05/06/21	Kenny/Darrell Mike	2301	Overlay road	15 flowboys 374 tons of D-mix from Wood Co.	120M, roscos roller
05/06/21	Devin	2704, cleaned trees out of creek, worked on 29			
05/07/21	Kevin/Bill	2303/2301/2311 2310	Repaired head wall 2303 /repaired base failures 2301, patched	7 yds rip rap, 14 yd concrete, 3 yds oil sand	Case backhoe, 23 22A
05/07/21	Ray/Devin	2714/2914/2709	Patched	3 yds oil sand	24
05/07/21	Kenny/Mike Darrell	2301	Overlay road	10 flowboys 250 tons of Wood County D-mix	120M, roscos roller
05/10/21	Devin	2628	Clean up down tree, changed covid sign, weed eat		Chainsaws
05/10/21	Chase/Woody	2302/2627	Patch	3 yds oil sand	24
05/10/21	Bill/Kevin Ray	2627/2628	Cut up tree, 2628, repaired base failures 2627	35 yds crushed concrete	Haul truck, case backhoe, 23, 26, 22, chainsaws

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used
- 19 -

05/10/21	Kenny/Mike Darrell	2627/2621	Blade roads	42 yds crushed concrete	120H, 27
05/11/21	Kenny/Mike	2404/2101/2102	Put up signs packed trash	4 post, 4 signs, stop sign, no thur truck	20R, backhoe
05/11/21	Devin	2512/2513	Cleaned up trees, worked on 24		24
05/11/21	Ray/Woody	2627/2629	Patched	2 ½ yds oil sand	22A
05/11/21	Bill/Kevin	2708/2705	Pick up mix from Malakoff, patched	2 yds oil sand	22
05/12/21	Chase/Woody	2437/2410/2801	Patch	4 yds oil sand	24
05/12/21	Bill/Kevin	2627/2416/2403 2414	Repaired base failures 2627, patched	14 yds crush concrete, 1 yd oil sand	22A
05/12/21	Kenny/Mike	2120/2627	Blade roads	35 yds crush concrete	27, 28, 120H
05/12/21	Ray/Devin	3443/2112/2146 2410	Repaired bridge on 3443, patched	2 yds oil sand	22
05/13/21	Bill/Kevin	2301/2412/2703 2719/2715/2725	Clean tree up 2301,patch	2 yds oil sand	Haul truck case backhoe, 23, 22A
05/13/21	Mike	Worked on equipment, push concrete			
05/13/21	Ray/Woody	2120/2301	Patched	3 yds oil sand	24
05/13/21	Devin	2318	Boomaxe		Boomaxe
05/14/21	Keivn/Bill	2500's	Patched	2 yds oil sand	22
05/14/21	Ray	2120	Patched, push up concrete	3 yds oil sand	24
05/14/21	Kenny/Mike Devin/Kevin	2301/2309	Overlay road	10 floyboys 255 tons Wood Co. D-mix	120M, Rosco roller

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used

- 20 -

05/17/21	Mike	Worked in shop, pushing up rock			Trex backhoe, SDLG
05/17/21	Devin	Worked on 22			
05/17/21	Ray/Woody	2621	Patched	1 yd oil sand	24
05/17/21	Bill/Kevin	2410/2402/2414 2511	Patched	2 yds oil sand	22B
05/18/21	Devin	2716	Boomaxe		Boomaxe
05/18/21	Ray/Woody	2112/2144/2139 2128/2143	Clean up trees patched	1 ½ yds oil sand	24
05/18/21	Bill/Kevin Kenny/Mike	2508/2506	Dug out ditches		Gradall, 26, 23, 27
05/19/21	Ray/Woody	2914/2501/2507 2621/2602/2914 2507/	Patched, cleaned up trees	4 yds oil sand	24
05/19/21	Bill/Kevin Mike	2506	Clean out road ditches		Gradall, 23, 26
05/19/21	Kenny/Darrell Devin	2216/2721/2434 2501	Patched cave ins, boomaxe, cut tree off 2902/2716	10 yds oil sand	120M, 27, 22, boomaxe
05/20/21	Chase/Easley	2501/2511/2904 2602	Patched, pick up tires	3 yds oil sand	24
05/20/21	Ray	2507/2504/2512 2404	Patched	3 yds oil sand	22
05/20/21	Bill/Kevin Mike	2506/2139	Clean out ditched 2506, repaired cross road culvert on 2139	7 yds old sand	Gradall, 23, 28
05/20/21	Kenny/Devin	2141/2501/2139	Boomaxe		Boomaxe
05/21/21	Kevin	2705	Boomaxe		Boomaxe
05/21/21	Ray	2621/2625/2627	Patch	2 yds oil sand	22
05/21/21	Bill/Kevin Devin/Ray	2112	Cut tree off road		Haultruck Caseback hoe, 23,25
05/21/21	Kenny/Mike	2124/2602/2502	Blade roads	7 yds concrete, 7 yds oil sand 14 yds millings	120H, 27
05/24/21	Ray	2120	Patch/shop	1 yds oil s	22

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material

*Oil Sand material is AC 20 Asphalt

Precinct 2-Daily Work Report

Date Employee County Roads Work Done Material Equip Used
- 21 -

05/24/21	Chase/Woody	2311/2304/2811 2806/2807	Patch	4 yds oil sand	24
05/24/21	Bill/Kevin	2319/2120/2119 2117/2511/2501 2502	Cleaned up tree and patched	2 yds oil sand	Case backhoe, haultruck, 25, 22A
05/24/21	Kenny/Mike	2702/2319	Boomaxe, cut tree up hauled off		Boomaxe

*Material used is in cubic yards or yds. 1 yd equals approx. 1.5 tons of material
 *Oil Sand material is AC 20 Asphalt